

# ASBESTOS-CONTAINING MATERIALS SURVEY REPORT

#### SUBJECT PROPERTY:

FEDERAL CORRECTIONAL INSTITUTION
DUBLIN CAMP DETENTION CENTER
UNITS A, B AND C
5701 8<sup>TH</sup> STREET,
DUBLIN, CALIFORNIA 94568

CONTRACT No. 15BDUB24P00000030

#### PREPARED FOR:

FEDERAL BUREAU OF PRISONS
FCI DUBLIN
REGIONAL FACILITIES ADMINISTRATOR WESTERN REGIONAL OFFICE
ATTN: DAVID DITTEMORE
7338 SHORELINE DRIVE,
STOCKTON, CALIFORNIA 95219

#### PREPARED BY:




**PROJECT No. 120316-AS** 

SURVEY DATE: FEBRUARY 27-29, 2024 REPORT DATE: MARCH 1, 2024 REVISED DATE: MARCH 14, 2024

Northern California 1901 Harrison Street, Suite 1100 Oakland, CA 94612 Corporate Office 1521 East Orangethorpe Ave., Suite B Fullerton, CA 92831 San Diego 2305 Historic Decatur Road Suite 100 San Diego, CA 92106

Office: 888-948-4826 Email: surveys@titan-enviro.com www.titan-enviro.com

5701 8th Street, Dublin, California 94568





## **TABLE OF CONTENTS**

1.0 EXECUTIVE SUMMARY	3
TABLE 1-1: IDENTIFIED ACMS	4
2.0 SURVEY PURPOSE AND SCOPE	6
2.1 Survey Purpose	6
3.0 ASBESTOS SAMPLING METHODOLOGY AND REGULATIONS	6
3.1 ASBESTOS SURVEY AND ANALYTICAL LABORATORY	6
3.2 ASBESTOS REGULATORY DEFINITIONS AND STANDARDS	7
4.0 SUSPECT ACM/ACCM SAMPLING ANALYTICAL RESULTS	10
4.1 ASBESTOS ANALYTICAL RESULTS SUMMARY	
4.2 SUSPECT ACMS/ACCMS NOT SAMPLED	11
4.3 Non-Suspect ACMs/ACCMs	11
5.0 CONCLUSIONS AND RECOMMENDATIONS	11
6.0 CERTIFICATION	12
7.0 LIMITATIONS	12
TABLES 14	
TABLE 4-1: ASBESTOS SAMPLING PLM ANALYTICAL RESULTS - UNIT B	
TABLE 4-1: ASBESTOS SAMPLING PLM ANALYTICAL RESULTS - UNIT A	
TABLE 4-1: ASBESTOS SAMPLING PLM ANALYTICAL RESULTS - UNIT C	19

#### **ATTACHMENTS**

ATTACHMENT I: LABORATORY ANALYTICAL REPORT(S)

ATTACHMENT II: CAD FLOOR PLAN DRAWING(S) ATTACHMENT III: INSPECTOR CERTIFICATION(S)

Document 246-2 Failed to Subject 246-2 Failed to Subject 246-2

Federal Correctional Institution – Dublin Camp Detention Center

Units A, B, and C 5701 8<sup>th</sup> Street, Dublin, California 94568

Project No. 120316-AS

March 14, 2024



#### 1.0 EXECUTIVE SUMMARY

Titan Environmental Solutions, Inc. (TES) was retained by David Dittemore, Regional Facilities Administrator at the Federal Bureau of Prisons (Client), to conduct and prepare an asbestos-containing materials survey report, This report focuses on the Federal Correctional Institution Dublin Camp Detention Center, including Units A, B, and C, located at 5701 8<sup>th</sup> Street, Dublin, California 94568 (referred to herein as the Subject Property).

The sampling included all accessible building/areas of the interior at the Subject Property. The asbestos-containing materials renovation survey was conducted in accordance with a mutually agreed upon proposal and scope of work.

The limited asbestos-containing materials survey was conducted on February 27-29, 2024 by Gabriel J. Klein, California Division of Occupational Safety and Health (DOSH/Cal-OSHA) Certified Asbestos Consultant (CAC No. 20-6831). The report was reviewed by Ibrahim M. Sobeih, DOSH/Cal-OSHA Certified Asbestos Consultant (CAC No. 06-4078) and Certified Industrial Hygienist (CIH) in the Comprehensive Practice by the Board for Global EHS Credentialing (BGC Certificate No. 5628CP).

The following summarizes the sampling and findings:

- The asbestos survey was performed in accordance with the EPA's National Emissions Standard for Hazardous Air Pollutants (NESHAP) and Bay Area Air Quality Management District (BAAQMD) Rule 2 asbestos regulations protocol for sample collection for demolition/renovation surveys, and sample analysis in accordance with EPA's "Method for the Determination of Asbestos in Bulk Building Materials" (EPA 600-R-93-116).
- During the survey, TES collected a total of two-hundred thirty-five (235) bulk samples of suspect Asbestos Containing Materials / Asbestos Containing Construction Materials (ACMs/ACCMs) representing seventy-five (75) identified homogenous areas in the survey area of the Subject Property, which were analyzed for asbestos content via Polarized Light Microscopy (PLM) visual estimation method.
- Material quantities provided in this report are for information purposes exclusively, and are
  not intended to be the basis of a contractor's bid for removal or abatement. Contractors are
  required to field verify materials and quantities for the purposes of bidding on contracted work.
- Asbestos was detected in the following samples collected in the survey area.

Federal Correctional Institution – Dublin Camp Detention Center

Units A, B, and C 5701 8<sup>th</sup> Street, Dublin, California 94568

Project No. 120316-AS March 14, 2024



#### TABLE 1-1: IDENTIFIED ACMS

HA No.	Sample No.	Sample Locations	Material Description	Class.	Material Location(s)*	Friable/ Non- Friable	Condition (G, D, SD)	Estimated Quantity*	Asbestos Analytical Results	BAAQMD Category
47	0227-47-143 0227-47-144 0227-47-145	Roof C W Wall Center Roof C W Wall Center Roof C W Wall Center	Black Seam Mastic	Misc.	Throughout Unit C Roof	NF	G	30 SF	7% Chrysotile	Category I ACM
52	0227-52-158 0227-52-159 0227-52-160	Roof C W Wall S End Roof C W Wall S End Roof C W Wall S End	Off-White Seam Mastic	Misc.	Throughout Unit C Roof	NF	G	20 SF	2% Chrysotile	Category I ACM
70	0227-70-218 0227-70-219 0227-70-220	Daily Stores E Wall N End Kitchen E Wall S End Kitchen S Wall Center	Off-White Door Seam Mastic	Misc.	Throughout Unit C Interior Around All Doors	NF	G	700 SF	2% Chrysotile	Category I ACM
74	0227-74-230 0227-74-231 0227-74-232	Boiler Room S Center Boiler Room S Center Boiler Room S Center	Black Duct Seam Mastic	Misc.	Within Unit C Interior on Rectangular HVAC Ducts	NF	G	250 SF	5% Chrysotile	Cateogy I ACM

#### Legend:

HA = Homogenous Material

N = North, E = East, W = West, S = South, SF = Square Feet, LF = Linear Feet, ND = None Detected Classification (Class.): Misc. = Miscellaneous, Surf. = Surfacing, TSI = Thermal System Insulation Condition: G = Good, D = Damaged, SD = Significantly Damaged Categories (Cat.):

- Cal/OSHA: ACCM = Asbestos Containing Construction Materials, ACM = Asbestos Containing Materials Class I, Class II, Class III, Class IV
- Presumed Asbestos Containing Material (PACM) = means thermal system insulation and surfacing material found in buildings constructed no later than 1980
- BAAQMD: Cat I = Category I Non-friable ACM, Cat II = Category II Non-friable ACM, RACM = Regulated Asbestos Containing Materials

\*\*In accordance with 40 CFR Section 61.141 and US EPA Applicability Determination Index Control Number: C112, if the amount by visual estimation appears to be less than 10 percent, the owner or operator may (1) assume the amount to be greater than 1 percent and treat the materials asbestos-containing material, or (2) require verification of the amount by point counting. If a result obtained by point count is different from a result obtained by visual estimation, the point count result will be used. Please note the Certified Asbestos Consultant will assume any material that is <1% analyzed via PLM and not verified by point count as an Asbestos Containing Material (ACM).

The third-party laboratory will discard all submitted samples after thirty (30) calendar days following receipt of the samples. Any additional analysis must be requested within thirty (30) days by the Client.

#### ASBESTOS-CONTAINING BUILDING MATERIALS

TES has the following recommendations based on the findings of the asbestos-containing building materials survey:

 The asbestos survey was performed in accordance with the EPA's NESHAP and BAAQMD Rule 2 asbestos regulations protocol for sample collection for demolition/renovation surveys and sample analysis in accordance with EPA's "Method for the Determination of Asbestos in Bulk Building Materials" (EPA 600-R-93-116).

<sup>\*</sup>The locations and quantities provided are estimates based solely on accessible materials within the survey area. There may be additional locations and quantities of asbestos-containing materials present at the Subject Property.

Document 246-2

Albest 64005 talking Materials Survel 25 port

Federal Correctional Institution - Dublin Camp Detention Center

Units A, B, and C

5701 8th Street, Dublin, California 94568

Project No. 120316-AS

March 14, 2024



- The survey included all relevant building materials, which are likely to be disturbed during the renovation project.
- A California licensed and DOSH/Cal-OSHA registered asbestos abatement contractor should be contracted to remove/abate ACMs/ACCMs and materials containing asbestos that are damaged or will be disturbed.
- A DOSH/Cal-OSHA Certified Asbestos Consultant should be contracted to conduct monitoring and clearance of any removal/abatement of ACMs/ACCMs and materials containing asbestos.
- Any ACMs/ACCMs that are in good condition and will not be disturbed during renovation or demolition activities shall be managed and maintained in accordance with all applicable regulatory standards to prevent potential exposure to these hazardous materials.
- Any materials that have not been identified in this report should be considered suspect ACMs/ACCMs and handled as ACM unless sampled by a DOSH/Cal-OSHA Certified Asbestos Consultant proven to be non-ACM by laboratory analysis.
- Material quantities provided in this report are for information purposes exclusively, and are not intended to be the basis of a contractor's bid for removal or abatement. Contractors are required to field verify materials and quantities for the purposes of bidding on contracted work.
- All asbestos activities must be performed in accordance with all applicable federal, state and local regulations including, but not limited to those summarized in this report.

Document 246-2 Failed to 400 Frailing Managers Survel/25 port

Federal Correctional Institution – Dublin Camp Detention Center

Units A, B, and C

5701 8<sup>th</sup> Street, Dublin, California 94568 Project No. 120316-AS

March 14, 2024



#### 2.0 SURVEY PURPOSE AND SCOPE

#### 2.1 SURVEY PURPOSE

- Collect bulk samples of suspect ACMs for demolition/renovation surveys in accordance with the NESHAP and BAAQMD Rule 2 asbestos regulations protocol for sample collection for demolition/renovation surveys and submit to an accredited laboratory for analysis. Analyze asbestos bulk samples using PLM visual estimation in accordance with EPA's July 1993 method (EPA 600/R-93/116) for the determination of asbestos in bulk building materials;
- Submit written report including analytical results, regulatory requirements, conclusions and recommendations.

The survey included a visual inspection and non-destructive testing methods to identify suspect materials that are readily accessible and visible. The survey did not involve removing building components or materials to access areas that are not visible or performing invasive testing that could damage the structure or equipment. As a result, there may be suspect materials that were not identified during the survey, particularly those that are concealed or inaccessible. It is important to keep this limitation in mind when interpreting the results of the survey and to take appropriate precautions when working with potentially hazardous materials. The survey included a visual inspection and non-destructive testing methods to identify suspect materials that are readily accessible and visible. The survey did not involve removing building components or materials to access areas that are not visible or performing invasive testing that could damage the structure or equipment. As a result, there may be suspect materials that were not identified during the survey, particularly those that are concealed or inaccessible. It is important to keep this limitation in mind when interpreting the results of the survey and to take appropriate precautions when working with potentially hazardous materials.

#### 3.0 ASBESTOS SAMPLING METHODOLOGY AND REGULATIONS

#### 3.1 ASBESTOS SURVEY AND ANALYTICAL LABORATORY

The asbestos survey was conducted in accordance with NESHAP pre-demolition standards. The asbestos survey consisted of two (2) primary field activities [(1) visual inspection of the survey area and (2) representative bulk sampling of suspect asbestos containing materials], laboratory sample analysis, and preparation of a survey report.

#### Asbestos Inspection

The visual inspection included the following activities: (1) identifying homogenous areas of suspect ACM, (2) determining friability and classification [surfacing = material that is spray or trowel applied, thermal system insulation (TSI) = material used to prevent heat gain/loss or condensation, or miscellaneous = material that is not surfacing or TSI] of each homogenous area of suspect ACM, (3) assessing the condition of each homogenous area of suspect ACM, and (4) quantifying each homogenous area of suspect ACM.

Document 246-2 Allows to 400 training Materials 5 whelve port

Federal Correctional Institution – Dublin Camp Detention Center

Units A, B, and C

5701 8th Street, Dublin, California 94568 Project No. 120316-AS

March 14, 2024



Visual inspection and physical handling is performed for all suspect materials to ensure proper friability classification, condition and potential damage - materials are assessed for any damage by impact, water, aging, deterioration, or delaminating from their substrata.

- Good Condition: Material with no visible damage, deterioration, or showing only very limited damage or deterioration.
- Damaged: The surface is crumbling, blistered, water stained, gouged, marred or otherwise abraded over less than one-tenth of the surface if the damage is evenly distributed; or less than one quarter if the damage is localized. Accumulation of powder, dust, or debris similar in appearance to the suspect material on surfaces beneath the material can be used as confirmatory evidence.
- Significantly Damaged: The surface is crumbling or blistered over at least one-tenth of the surface if the damage is evenly distributed or at least one quarter if the damage is localized; and water stains, gouges or mars over at least one-tenth of the surface if the damage is evenly distributed or at least one quarter if the damage is localized. Accumulation of powder, dust, or debris similar in appearance to the suspect material on surfaces beneath the material can be used as confirmatory evidence.

#### Asbestos Sample Analysis

Upon completion of the bulk sampling activities, the samples were submitted to an accredited laboratory by the National Institute for Standards and Technology (NIST) under the National Voluntary Laboratory Accreditation Program (NVLAP), under proper Chain-of-Custody (COC) documentation. Bulk sample analysis was conducted by Polarized Light Microscopy (PLM) with dispersion staining as described in the "Method for the Determination of Asbestos in Bulk Building Materials," Method EPA-600/R-93/116 (July 1993, Part 1). A sample is immersed in a solution of known refractive index and subjected to illumination by polarized light.

TES collected two-hundred thirty-five (235) bulk samples of suspect ACMs/ACCMs representing sevety-five (75) homogenous areas from the survey area of the Subject Property, which were analyzed for asbestos content via Polarized Light Microscopy (PLM) visual estimation by Eurofins EPK Built Environment Testing, LLC. in Tustin, California. Eurofins EPK Built Environment Testing, LLC. is accredited by the National Institute for Standards and Technology (NIST) under the National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 200757-0).

#### 3.2 ASBESTOS REGULATORY DEFINITIONS AND STANDARDS

#### Asbestos Regulatory Definitions

The Environmental Protection Agency (EPA) defines asbestos-containing material (ACM) as follows:

**ACM** is defined by EPA as any material containing more than one percent (>1%) asbestos as determined using the method specified in Section 1, Appendix E of 40 CFR Part 763 Subpart E, Polarized Light Microscopy (PLM). In order to verify a material with detected concentrations of asbestos is not an ACM, the EPA requires PLM point count analysis to confirm the asbestos concentration is <1.0%.

Document 246-2 Failed to 405 lang Manglas & well 25 port

Federal Correctional Institution – Dublin Camp Detention

Units A, B, and C 5701 8th Street, Dublin, California 94568

> Project No. 120316-AS March 14, 2024



- Friable ACM as defined by the EPA, means material containing more than one percent (>1%)
  as determined by PLM that when dry, may be crumbled, pulverized, or reduced to powder by
  hand pressure, and includes previously non-friable material after such previously non-friable
  material becomes damaged to the extent that when dry it may be crumbled, pulverized, or
  reduced to powder by hand pressure.
- Non-friable ACM as defined by the EPA, means material containing more than one percent (>1%) as determined by PLM that when dry, may NOT be crumbled, pulverized, or reduced to powder by hand pressure. NESHAP and BAAQMD further defines two (2) categories of non-friable ACM:
  - Category I (Cat I) Category I Non-friable ACM is any asbestos-containing packing, gasket, resilient floor covering, mastic or asphalt roofing product which contains more than one percent (>1%) asbestos as determined using PLM according to the method specified in Appendix E, Subpart E, 40 CFR Part 763.
  - Category II (Cat II) Category II Non-friable ACM is any material, excluding Category I non-friable ACM, containing more than one percent (>1%) asbestos as determined using PLM according to the method specified in Appendix E, Subpart E, 40 CFR Part 763 that, when dry, cannot be crumbled, pulverized, or reduced to powder by hand pressure.
  - Regulated Asbestos-Containing Material (RACM) is defined by NESHAP and BAAQMD as Friable ACM, Category I Non-friable ACM that has become friable, Category I Non-friable ACM that will be or has been subjected to sanding, grinding, cutting or abrading, or Category II Non-friable ACM that has a high probability of becoming or has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material in the course of demolition or renovation operations.

Federal Occupational Safety and Health Administration (OSHA) and the California Division of Occupational Safety and Health (DOSH/Cal-OSHA) Classes of Asbestos Work as codified in 29 CFR 1926.1101 and 8 CCR 1529, respectively:

- Class I Asbestos work means activities involving the removal of TSI and surfacing ACM and PACM.
- Class II Asbestos work means activities involving the removal of ACM which is no thermal system insulation or surfacing materials. This includes, but is not limited to, the removal of asbestos-containing wallboard, floor tile and sheeting, roofing and siding shingles, and construction mastics / adhesives.
- Class III Asbestos work means repair and maintenance operations, where "ACM", including TSI and surfacing ACM and PACM, is likely to be disturbed.

Document 246-2 Failed to 405 landing Managers Sunt et 25 port

Federal Correctional Institution – Dublin Camp Detention Center

Units A, B, and C 5701 8<sup>th</sup> Street, Dublin, California 94568

Project No. 120316-AS March 14, 2024



• Class IV Asbestos work means maintenance and custodial activities during which employees contact, but do not disturb, ACM or PACM and activities to clean up dust, waste and debris resulting from Class I, II, and III activities.

The Federal Occupational Safety and Health Administration (OSHA) and the California Division of Occupational Safety and Health (DOSH/Cal-OSHA) use the following definitions for materials containing asbestos:

- **ACM** is defined by OSHA and DOSH/Cal-OSHA as any material containing more than one percent (>1%) asbestos.
- Asbestos-containing construction material (ACCM) is defined by DOSH/Cal-OSHA as any
  manufactured construction material containing greater than one tenth of one percent (>0.1%)
  asbestos.
- **Material Containing Asbestos** OSHA and DOSH/Cal-OSHA regulate materials containing any detectable concentrations of asbestos.

### Asbestos Regulatory Standards Summary

NESHAP, OSHA, DOSH/Cal-OSHA, the California Department of Toxic Substance Control (DTSC) and local air quality/pollution control districts regulate the removal, disturbance and disposal of asbestos in California. The following is a brief list of these, not all, applicable regulatory standards:

- Cat I and II/Class I and II Non-Friable ACM (>1% asbestos):
  - NESHAP and local air quality/pollution control districts require the abatement/removal of ACM, both friable and non-friable in California, prior to renovation or demolition activities which would disturb them. The abatement/removal must be performed in accordance with the local air quality/pollution control district regulatory standard, including containment and notification as applicable.
  - DOSH/Cal-OSHA requires abatement/removal of ACM to be performed by a California licensed and DOSH/Cal-OSHA registered asbestos abatement contractor using work practices in accordance with the standards prescribed in 8 CCR 1529.
  - Federal OSHA requires abatement/removal of ACM to be performed in accordance with the standards prescribed in 29 CFR 1926.1101.
  - DTSC requires disposal of non-friable ACM that remains substantially intact as a Non-Friable/Non-Hazardous Asbestos Waste in California.

Document 246-2 Falsods No. 105 Marking Manageaus Louve J. R. Sport

Federal Correctional Institution – Dublin Camp Detention Center Units A, B, and C

> 5701 8<sup>th</sup> Street, Dublin, California 94568 Project No. 120316-AS

March 14, 2024



### • Friable ACM/RACM (friable, >1% asbestos):

- NESHAP and local air quality/pollution control districts require the abatement/removal of ACM, both friable and non-friable in California, prior to renovation or demolition activities which would disturb them. The abatement/removal must be performed in accordance with the local air quality/pollution control district regulatory standard, including containment and notification as applicable.
- DOSH/Cal-OSHA requires abatement/removal of ACM to be performed by a California licensed and DOSH/Cal-OSHA registered asbestos abatement contractor using work practices in accordance with the standards prescribed in 8 CCR 1529.
- Federal OSHA requires abatement/removal of ACM to be performed in accordance with the standards prescribed in 29 CFR 1926.1101.
- DTSC requires disposal of friable ACM as a Friable/Hazardous Asbestos Waste in California.

#### ACCM (>0.1% asbestos):

- DOSH/Cal-OSHA requires disturbance/removal of ACCM to be performed using properly trained workers and special work practices in accordance with the standards prescribed in 8 CCR 1529.
- DOSH/Cal-OSHA requires a "report of use" for disturbance/removal of ACCM (8 CCR 5203) and further requires a DOSH/Cal-OSHA registered contractor for disturbance/removal of 100 square feet or more of ACCM (California Labor Code 6500-6510).

#### Material containing asbestos (<0.1% asbestos):</li>

 OSHA and DOSH/Cal-OSHA requires disturbance/removal of materials containing asbestos to be performed using properly trained workers and special work practices in accordance with the standards prescribed in 29 CFR 1926.1101 and 8 CCR 1529.

#### 4.0 SUSPECT ACM/ACCM SAMPLING ANALYTICAL RESULTS

## 4.1 ASBESTOS ANALYTICAL RESULTS SUMMARY

Tables 4-1 - Unit A, Table 4-1 - Unit B and Table 4-1 - Unit C provide a summary of suspect ACM/ACCM samples analytical results.

Document 246-2

FALSOGS 103/05/12/Aing Materials Survey Report

Federal Correctional Institution - Dublin Camp Detention Center

Units A, B, and C 5701 8th Street, Dublin, California 94568

Project No. 120316-AS

March 14, 2024



#### 4.2 SUSPECT ACMS/ACCMS NOT SAMPLED

The suspect ACMs/ACCMs listed below may be present at the Subject Property and due to the nondestructive nature of this survey were not sampled in order to avoid (1) hazardous conditions, (2) impacting the integrity of the structure, (3) damaging building materials and finishes that cannot be easily repaired, (4) damaging equipment and/or mechanical systems, (5) voiding warranties, and/or (6) creating hazards including, but not limited to, an asbestos fiber release episode. If any of the following materials are identified at the Subject Property, these materials should be considered ACMs unless a DOSH/Cal-OSHA CAC determines they are not asbestos containing.

- Inaccessible and/or concealed materials including, but not limited to:
  - Glues 0
  - Pipe coal tar wrapping, pipe coating, bituminous wrapping, resin wrapping

#### 4.3 Non-Suspect ACMs/ACCMs

The non-suspect ACMs/ACCMs listed below may be present at the Subject Property and were not sampled because they were determined to be non-suspect by a DOSH/Cal-OSHA CAC.

- Fiberglass: insulation, etc.;
- Glass: windows, doors, mirrors, etc.;
- Laminate/faux wood: flooring, wall covering, etc.;
- Metal materials/finishes: door and window framing, ducting, etc.;
- Terrazzo: flooring, wall covering, etc.; and
- Wood materials/finishes: flooring, wall paneling, framing, etc.

#### 5.0 **CONCLUSIONS AND RECOMMENDATIONS**

TES has the following conclusions and recommendations based on the findings of the asbestoscontaining building materials survey:

- The asbestos survey was performed in accordance with the EPA's NESHAP and BAAQMD Rule 2 asbestos regulations protocol for sample collection for demolition/renovation surveys and sample analysis in accordance with EPA's "Method for the Determination of Asbestos in Bulk Building Materials" (EPA 600-R-93-116).
- The survey included all relevant building materials, which are likely to be disturbed during the renovation project.
- A California licensed and DOSH/Cal-OSHA registered asbestos abatement contractor should be contracted to remove/abate ACMs/ACCMs and materials containing asbestos that are damaged or will be disturbed.

Federal Correctional Institution - Dublin Camp Detention Center

Units A, B, and C 5701 8th Street, Dublin, California 94568

Project No. 120316-AS March 14, 2024



- A DOSH/Cal-OSHA Certified Asbestos Consultant should be contracted to conduct monitoring and clearance of any removal/abatement of ACMs/ACCMs and materials containing asbestos.
- Any ACMs/ACCMs that are in good condition and will not be disturbed during renovation
  or demolition activities shall be managed and maintained in accordance with all applicable
  regulatory standards to prevent potential exposure to these hazardous materials.
- Any materials that have not been identified in this report should be considered suspect ACMs/ACCMs and handled as ACM unless sampled by a DOSH/Cal-OSHA Certified Asbestos Consultant proven to be non-ACM by laboratory analysis.
- Material quantities provided in this report are for information purposes exclusively, and are not intended to be the basis of a contractor's bid for removal or abatement. Contractors are required to field verify materials and quantities for the purposes of bidding on contracted work.
- All asbestos activities must be performed in accordance with all applicable federal, state and local regulations including, but not limited to those summarized in this report.

#### 6.0 CERTIFICATION

This sampling, including preparation of this report, was conducted under the direction of Robert Menald (CAC No. 08-4323) and Ibrahim M. Sobeih (CAC No. 06-4078 and CIH in the Comprehensive Practice by the Board for Global EHS Credentailing [BGC Certificate No. 5628CP]), undersigned. If you have any questions or require any additional information or services, please contact our office toll free at (888) 948-4826.

Sincerely,

Titan Environmental Solutions, Inc.

Robert Menáld, CIEC, CAC, LRCIA

Project Manager

Ibrahim M. Sobeih, MS, MSPH, CIH, CAC, FAIHA Director of Industrial Hygiene and Safety

#### 7.0 LIMITATIONS

TES is committed to providing state-of-the-art environmental consulting services that are of the highest quality. However, asbestos-containing materials survey work is not an exact science. The possibility of field and general conditions beyond TES control that affect our work or that present a concern for the safety of our employees, our consultants, building occupants and the public at the

Document 246-2

FALSOGS 104/05/12/Aing Managia ISUN EVER Sport

Federal Correctional Institution – Dublin Camp Detention Center

Units A, B, and C 5701 8<sup>th</sup> Street, Dublin, California 94568

Dublin, California 94568 Project No. 120316-AS





site, and insurance constraints, requires that we qualify the services we provide with the following limitations:

- In accordance with the client specified scope of work, this survey was limited to accessible building materials and areas at the Subject Property identified by the Client; no destructive investigation was performed. Additional suspect materials located inaccessible areas and/or outside the scope of this survey may be present at the Subject Property.
- Reasonable effort is made by TES personnel to locate and sample all suspect hazardous materials. However, for any building there is the possibility that various types of unique or concealed hazardous materials may exist undetected. In addition, sampling and laboratory analyses constraints typically hinder the investigation. TES does not warrant, guarantee or profess to have the ability to locate or identify all hazardous materials in a building.
- Confined spaces and areas determined by TES personnel to be unsafe to access, are excluded from the scope of work.
- TES is not, and has no responsibility as, a generator, operator, treater, storer, transporter or disposer of hazardous materials or waste found or identified as a result of TES work.
- TES does not guarantee or warrant that the Subject Property or workplace are safe, nor
  does TES involvement in this property relieve the Client, building owner/operator or tenant of
  any continuing responsibility of providing a safe property or workplace.
- This report was based on those conditions observed on the day(s) the field evaluation was accomplished. In the event that changes in the nature of the property have occurred, or additional relevant information about the property is subsequently discovered, the findings and recommendations contained in this report may not be valid unless these changes and additional relevant information are reviewed and the conclusion of this report is modified and verified in writing.
- It is understood that the survey is a non-destructive assessment of potential hazardous materials and is to be used expressly for the purpose of evaluating the risk relative to the expected material disturbance at the Subject Property. Because destructive investigation has not been performed during the survey, the report may not reveal concealed hazardous materials. Subsequently, additional investigation including construction documents review and/or destructive investigation is recommended as a precaution to prevent accidental exposure when construction or demolition is planned for this Subject Property.
- It is understood that this is a modified survey and results are limited to the specific areas and materials sampled. This report is not valid for use outside of the specific areas identified by the Client or by individuals not associated with the currently planned work at the Subject Property.



## **TABLES**



#### TARLE 4-1: ASBESTOS SAMPLING PLM ANALYTICAL RESULTS - UNIT B

2		TABLE 4-1	: Asbestos S	AWIFEIN	GI EM ANAL	T TICAL IN	30213 - 01			
HA No.	Sample No.	Sample Location	Material Description	Class.	Material Location(s)*	Friable Non- Friable	Condition (G, D, SD)	Estimated Quantity*	Asbestos Analytical Results	BAAQMD Cat.
	0227-01-01	Roof B SW Comer	Black							
01	0227-01-02	Roof B NW Corner	Penetration	Misc.	Roof B	NF	G	75 SF	None Detected	Non-ACM
	0227-01-03	Roof B NE Corner	Mastic				s*			s <sup>*</sup>
	0227-02-04	Roof B S Center		8			2,	8	200000000000000000000000000000000000000	4
02	0227-02-05	Roof B S Center	Gray Seam Mastic	Misc.	Roof B	NF	G	30 SF	None Detected	Non-ACM
	0227-02-06	Roof B SE End	,,,aou						20100100	
	0227-03-07	Roof B SW End	Off-White /						(550)	
03	0227-03-08	Roof B W Center	Gray Roof Flashing	Misc.	Roof B	NF	G	260 SF	None Detected	Non-ACM
	0227-03-09	Roof E N End	Caulking						Detected	
	0227-04-10	Roof B W Center	Off White /							
04	0227-04-11	Roof B NE Corner	Off-White / Gray Exterior	Misc.	Roof B Parapet Wall	NF	G	780 SF	None Detected	Non-ACM
	0227-04-12	Roof B E Wall Center	Wall Texture		i diapet wali		77		Detected	
	0227-05-13	Roof B Center					Z <sub>i</sub>	8 8		4
05	0227-05-14	Roof B Center	Black Sealant	Misc.	Roof B Skylight	NF	G	85 SF	None Detected	Non-ACM
	0227-05-15	Roof B Center	1		Skylight				Detected	
	0227-06-16	Roof B NE Corner			- 10	2	SV.			2
06	0227-06-17	Roof B NE Corner	Gray HVAC	Misc.	Roof B HVAC	NF	G	70 SF	None Detected	Non-ACM
10210	0227-06-18	Roof B NE Corner	Mastic		System			1000000000		zero-samelbiti vocado
	0227-07-19	Roof B S Center					22			
07	0227-07-20	Roof B Center	Black Roof Mastic	Misc.	Roof B	NF	G	130 SF	None Detected	Non-ACM
	0227-07-21	Roof B Center	Wasuc	name.					Detected	
	0227-08-22	Unit B Shower 1 W Wall				2	0,			2
08	0227-08-23	Unit B Shower 1 E Wall	White Drywall / Joint	Misc.	Unit B	F	G	975 SF	None	Non-ACM
	0227-08-24	Unit B Shower 2 W Wall	Compound		Interior				Detected	
	0227-09-25	2nd Floor Corridor SW	,			120	DV		963	36 S
09	0227-09-26	2nd Floor Corridor SW	White 2'x2'	Misc.	Unit B	F	G	1,200 SF	None	Non-ACM
	0227-09-27	2nd Floor Corridor SW	Ceiling Tile		Interior			10.	Detected	
	0227-10-28	B211 W Wall Center								
10	0227-10-29	B237 N Wall Center	Tan Cove	Misc.	Unit B	NF	G	1,100 SF	None	Non-ACM
.00.000	0227-10-30	B113 W Wall Center	Base Mastic	Data Market	Interior		16060	0.000.000000	Detected	
	0227-11-31	B216 Floor Center	ĺ	3		3		6		
11	0227-11-32	B221 Floor Center	Gray 9"x9"	Misc.	Unit B	NF	G	5,890 SF	None	Non-ACM
	0227-11-33	B122 Floor Center	Vinyl Floor Tile		Interior				Detected	
	0227-12-34	1st Floor Corridor SE						-	7	
12	0227-12-35	1st Floor Corridor W Center	White 9"x9" Vinyl Floor Tile	Misc.	Unit B Interior	NF	G	530 SF	None Detected	Non-ACM
	0227-12-36	1st Floor Corridor NE	6							
	0227-13-37	B219 Floor Center								
13	0227-13-38	B121 Floor Center	Black Floor Mastic	Misc.	Unit B Interior	NF	G	6,370 SF	None Detected	Non-ACM
	0227-13-39	B122 Floor Center	ividSUC		IIIICHUI			***************************************	Detected	

TITAN ENVIRONMENTAL SOLUTIONS Asbestos-Containing Materials Survey Report Federal Correctional Institution – Dublin Camp Detention Center Units A, B, and C 5701 8<sup>th</sup> Street, Dublin, California 94568 Project No. 120316-AS March 14, 2024

										lu i
	0227-14-40	Shower 1 N Wall Center			20000					
14	0227-14-41	Shower 2 N Wall Center	Gray Concrete	Misc.	Unit B Interior	NF	G	12,000 SF	None Detected	Non-ACM
	0227-14-42	Laundry Room S Wall Center					6			65
	0227-15-43	1st Floor Corridor N								
15	0227-15-44	1st Floor Corridor N	White 9"x9" Ceiling Tile	Misc.	Unit B Interior	F	G	220 SF	None Detected	Non-ACM
	0227-15-45	1st Floor Corridor N	3		(19000000000000000000000000000000000000					
	0227-16-46	Shower 1 N Wall Center	85	33	540095000000	50	38		500000000000000000000000000000000000000	38
16	0227-16-47	Shower 2 N Wall Center	Gray Plaster	Misc.	Unit B Interior	NF	G	980 SF	None Detected	Non-ACM
	0227-16-48	Janitor E Wall Center								
	0227-17-49	Laundry Room S Wall Center			U-4.B					
17	0227-17-50	Laundry Room S Wall Center	White Pipe Insulation	TSI	Unit B Laundry Room	F	G	60 SF	None Detected	Non-ACM
	0227-17-51	Laundry Room S Wall Center		s2	Room		vi	2 8		
	0227-18-52	1st Floor Corridor N	95 95 95 95 75 75 75 75 75 75 75 75	33 3	0410995000000	58 5.	38		800 800 800 800 800 800 800 800 800 800	08
18	0227-18-53	1st Floor Corridor N	Brown Puck Mastic	Misc.	Unit B Interior	NF	G	220 SF	None Detected	Non-ACM
	0227-18-54	1st Floor Corridor N								
	0227-19-55	Laundry Room S Center			Unit B				(88)	
19	0227-19-56	Laundry Room S Center	Tan HVAC Duct Mastic	Misc.	Laundry	NF	G	40 SF	None Detected	Non-ACM
	0227-19-57	Laundry Room S Center		17 A	Room					100
	0227-20-58	B141 Cell Door	Black Cell							
20	0227-20-59	B139 Cell Door	Window	Misc.	Unit B Interior	NF	G	170 SF	None Detected	Non-ACM
	0227-20-60	B117 Cell Door	Caulking							
	0227-21-61	1 Floor Corridor W Wall N End	į.							
21	0227-21-62	1 Floor Corridor W Wall N End	Red Electrical Mastic	Misc.	Unit B Interior	NF	G	20 SF	None Detected	Non-ACM
	0227-21-63	1 Floor Corridor W Wall N End								
	0227-22-64	Roof B SW								
22	0227-22-65	Roof B NW Corner	Black Rolled Roof System	Misc.	Roof B	NF	G	12,000 SF	None Detected	Non-ACM
	0227-22-66	Roof B E Center								
			-							

#### Legend:

HA = Homogenous Material

N = North, E = East, W = West, S = South, SF = Square Feet, LF = Linear Feet, ND = None Detected Classification (Class.): Misc. = Miscellaneous, Surf. = Surfacing, TSI = Thermal System Insulation Condition: G = Good, D = Damaged, SD = Significantly Damaged Categories (Cat.):

- · CalOSHA: ACCM = Asbestos Containing Construction Materials, ACM = Asbestos Containing Materials Class II, Class III, Class IV,
- Presumed Asbestos Containing Material (PACM) = means thermal system insulation and surfacing material found in buildings constructed no later than 1980
- BAAQMD: Cat I = Category I Non-friable ACM, Cat II = Category II Non-friable ACM, RACM = Regulated Asbestos Containing Materials

The third-party laboratory will discard all submitted samples after thirty (30) calendar days following receipt of the samples. Any additional analysis must be requested within thirty (30) days by the Client.

<sup>\*</sup>The locations and quantities provided are estimates based solely on accessible materials within the survey area. There may be additional locations and quantities of asbestos-containing materials present at the Subject Property.

<sup>\*\*</sup>In accordance with 40 CFR Section 61.141 and US EPA Applicability Determination Index Control Number: C112, if the amount by visual estimation appears to be less than 10 percent, the owner or operator may (1) assume the amount to be greater than 1 percent and treat the materials asbestos-containing material, or (2) require verification of the amount by point counting. If a result obtained by point count is different from a result obtained by visual estimation, the point count result will be used. Please note the Certified Asbestos Consultant will assume any material that is <1% analyzed via PLM and not verified by point count as an Asbestos Containing Material (ACM).



#### TABLE 4-1: ASBESTOS SAMPLING PLM ANALYTICAL RESULTS - UNIT A

HA No.	Sample No.	Sample Location	Material Description	Class.	Material Location(s)*	Friable Non-	Condition (G, D, SD)	Estimated Quantity*	Asbestos Analytical	BAAQMD Cat.
	0227-23-67	Unit A Roof Center	•		, ,	Friable			Results	
23	0227-23-68	Unit A Roof Center	Black Penetration	Misc.	Unit A Roof	NF	G	75 SF	None	Non-ACM
20	0227-23-69	Unit A Roof Center	Mastic	Wilde.	OnicArtoor	141		7001	Detected	HOIPAOM
-	0227-24-70	Unit A Roof Center	- 50							
24	0227-24-70	Unit A Roof Center	Black	Misc.	Unit A Roof	NF	G	85 SF	None	Non-ACM
24	0227-24-71	Unit A Roof Center	Sealant	IVIISC.	Skylight	INF	G	00 31	Detected	NOII-ACIVI
	0227-24-72	Unit A Roof W Center	ox.							
25	0227-25-73	Unit A Roof W Center	Gray HVAC	Micc	Unit A Roof	NF	G	70 SF	None	Non ACM
25	A STATE OF THE STATE OF T		Mastic	Misc.	HVAC Unit	INF	G	70 SF	Detected	Non-ACM
	0227-25-75	Unit A Roof W Center	S <sup>2</sup>	2				8		
12160	0227-26-76	Unit A Roof E Center	Black Roof	Progression of the Progression o		0000		9957000	None	neverse majori
26	0227-26-77	Unit A Roof Center	Mastic	Misc.	Unit A Roof	NF	G	120 SF	Detected	Non-ACM
	0227-26-78	Unit A Roof Center								
1593	0227-27-79	Unit A Roof S Wall Center	Off-White	7250	Unit A Roof	1905		Service Service	None	735 97720
27	0227-27-80	Unit A Roof S Wall W End	Wall Texture	Misc.	Parapet Wall	NF	G	780 SF	Detected	Non-ACM
	0227-27-81	Unit A Roof N Wall Center	TOXICIO							
	0227-28-82	Unit A Roof E Wall S End	Tan						None	
28	0227-28-83	Unit A Roof S Wall Center	Flashing Caulking	Misc.	Unit A Roof	NF	G	260 SF	None Detected	Non-ACM
	0227-28-84	Unit A Roof W Wall Center	Caulking	2				8.		
2	0227-29-85	Unit A Roof Center	Black						THE PAST AND A	
29	0227-29-86	Unit A Roof Center	Rolled Roof	Misc.	Unit A Roof	NF	G	12,000 SF	None Detected	Non-ACM
	0227-29-87	Unit A Roof Center	System							
	0227-30-88	Shower 1 S Wall Center								
	0227-30-89	Shower 1 S Wall Center	White							
30	0227-30-90	Shower 1 N Wall Center	Drywall / Joint	Misc.	Unit A Interior	F	G	1,300 SF	None Detected	Non-ACM
	0227-30-91	Shower 1 N Wall Center	Compound						Detected	
	0227-30-92	Shower 2 N Wall Center	1							
	0227-31-93	2nd Floor S Corridor E End								
31	0227-31-94	2nd Floor S Corridor E End	White 2'x2'	Misc.	Unit A Interior	F	G	1,200 SF	None Detected	Non-ACM
100.00	0227-31-95	2nd Floor N Corridor E End	Ceiling Tile	3.400.000				PARK VICE EACH	Detected	
	0227-32-96	1st Floor Day Room SE	3							
32	0227-32-97	1st Floor Day Room SE	Tan Cove	Misc.	Unit A Interior	NF	G	1,100 SF	None	Non-ACM
1000	0227-32-98	1st Floor Day Room NW	Base Mastic		11 1 10 10 10 10 10 10 10 10 10 10 10 10			10.400.000.000	Detected	**************************************
3	0227-33-99	A140 Floor Center	(s) (c)	5				<u> </u>		
33	0227-33-100	N Corridor Floor W End	Gray 9"x9" Vinyl Floor	Misc.	Unit A Interior	NF	G	5,790 SF	None	Non-ACM
10.110	0227-33-101	S Corridor Floor W End	Tile		V F A MAZDAMAN NA POSITA ZARRON PROPRINCIA MANAGAMAN AND AND AND AND AND AND AND AND AND A			200 • 000 200 200 200 200 200 200 200 20	Detected	
	0227-34-102	S Corridor Floor Center	M/bit- 0" 0"							
34	0227-34-103	W Corridor Floor S End	White 9"x9" Vinyl Floor	Misc.	Unit A Interior	NF	G	600 SF	None	Non-ACM
	0227-34-104	Day Room Floor Center	Tile		The second of th		G	remains docted in	Detected	normal development of the H
	0227-35-105	A138 Floor Center	Riug O"vO"		SECOLO SON CONTROL SIN				Water	
35	0227-35-106	A138 Floor Center	Blue 9"x9" Vinyl Floor	Misc.	Unit A Interior A138	NF	G	100 SF	None Detected	Non-ACM
	0227-35-107	A138 Floor Center	Tile		A130		1		Detected	I



	0227-36-108	A117 Floor Center	P. A. Secul Property and the property						Management	
36	0227-36-109	A120 Floor Center	Black Floor Mastic	Misc.	Unit A Interior	NF	G	6,370 SF	None Detected	Non-ACM
	0227-36-110	A121 Floor Center	L-MAXIME QUIDINGS						U.S.J. 7.63970-03 (3-605) 1-06	
	0227-37-111	Laundry Room E Wall Center	DE DESCRIPTION		2				100000000000000000000000000000000000000	
37	0227-37-112	Laundry Room E Wall Center	Gray Concrete	Misc.	Unit A Interior	NF	G	12,000 SF	None Detected	Non-ACM
	0227-37-113	Laundry Room E Wall Center								
	0227-38-114	W Corridor Ceiling Center	200							
38	0227-38-115	W Corridor Ceiling Center	White 9"x9" Ceiling Tile	Misc.	Unit A Interior	F	G	220 SF	None Detected	Non-ACM
	0227-38-116	W Corridor Ceiling Center						,,	And an about the latest Cally	
	0227-39-117	W Corridor Ceiling Center								
39	0227-39-118	W Corridor Ceiling Center	Brown Puck Mastic	Misc.	Unit A Interior	NF	G	220 SF	None Detected	Non-ACM
	0227-39-119	W Corridor Ceiling Center	maotio						Dottoutou	
	0227-40-120	Shower 2 N Wall Center	58		9	7				
	0227-40-121	Shower 2 S Wall Center								
40	0227-40-122	Shower 1 N Wall Center	Gray Plaster	Misc.	Unit A Interior	NF	G	26,000 SF	None Detected	Non-ACM
	0227-40-123	Shower 1 S Wall Center	600.00000,0000							
	0227-40-124	A138 E Wall S End								
	0227-41-125	Laundry Room NE Corner	138 *188000001001 10000		Unit A Interior				8003	
41	0227-41-126	Laundry Room NE Corner	White Pipe Insulation	TSI	Laundry	F	G	130 SF	None Detected	Non-ACM
	0227-41-127	Laundry Room NE Corner			Room					
	0227-42-128	Laundry Room SE Corner	2.	is .	11-3 6 1-1-2-					
42	0227-42-129	Laundry Room SE Corner	Tan HVAC Mastic	Misc.	Unit A Interior Laundry	NF	G	45 SF	None Detected	Non-ACM
	0227-42-130	Laundry Room SE Corner	Mastic		Room				Detected	
	0227-43-131	A209 Cell Window								
43	0227-43-132	A222 Cell Window	<ul> <li>Black Cell Window</li> </ul>	Misc.	Unit A Interior	NF	G	170 SF	None Detected	Non-ACM
	0227-43-133	A234 Cell Window	Caulking						Detected	
	0227-44-134	2nd Floor Corridor W End								
44	0227-44-135	2nd Floor Corridor W End	Red Electrical	Misc.	Unit A Interior	NF	G	20 SF	None	Non-ACM
	0227-44-136	2nd Floor Corridor W End	Mastic				the state of	000073030000000	Detected	L-VANDAGO CONTRACTOR OF THE CO
	35855B \$1595A86A					L	L			

#### Legend:

HA = Homogenous Material

N = North, E = East, W = West, S = South, SF = Square Feet, LF = Linear Feet, ND = None Detected Classification (Class.): Misc. = Miscellaneous, Surf. = Surfacing, TSI = Thermal System Insulation Condition: G = Good, D = Damaged, SD = Significantly Damaged Categories (Cat.):

- CalOSHA: ACCM = Asbestos Containing Construction Materials, ACM = Asbestos Containing Materials Class I, Class II, Class IV
- Presumed Asbestos Containing Material (PACM) = means thermal system insulation and surfacing material found in buildings constructed no later than 1980
- BAAQMD: Cat I = Category I Non-friable ACM, Cat II = Category II Non-friable ACM, RACM = Regulated Asbestos Containing Materials

The third-party laboratory will discard all submitted samples after thirty (30) calendar days following receipt of the samples. Any additional analysis must be requested within thirty (30) days by the Client.

<sup>\*</sup>The locations and quantities provided are estimates based solely on accessible materials within the survey area. There may be additional locations and quantities of asbestos-containing materials present at the Subject Property.

<sup>\*\*</sup>In accordance with 40 CFR Section 61.141 and US EPA Applicability Determination Index Control Number: C112, if the amount by visual estimation appears to be less than 10 percent, the owner or operator may (1) assume the amount to be greater than 1 percent and treat the materials asbestos-containing material, or (2) require verification of the amount by point counting. If a result obtained by point count is different from a result obtained by visual estimation, the point count result will be used. Please note the Certified Asbestos Consultant will assume any material that is <1% analyzed via PLM and not verified by point count as an Asbestos Containing Material (ACM).



#### TABLE 4-1: ASBESTOS SAMPLING PLM ANALYTICAL RESULTS - UNIT C

HA No.	Sample No.	Sample Location	Material Description	Class.	Material Location(s)*	Friable Non- Friable	Condition (G, D, SD)	Estimated Quantity*	Asbestos Analytical Results	BAAQMD Cat.
	0227-45-137	Roof C W Wall S End								
45	0227-45-138	Roof C W Wall N End	Gray Wall Texture	Misc.	Unit C Roof	NF	G	900 SF	None Detected	Non-ACM
9	0227-45-139	Roof C N Wall Center	T OME O				8 50	X.	Dolodio	
	0227-46-140	Roof C W Center	Black		8		\$	ž	8	
46	0227-46-141	Roof C Center	Rolled Roof	Misc.	Unit C Roof	NF	G	9,000 SF	None Detected	Non-ACM
	0227-46-142	Roof N Center	System					38	Dottotted	
	0227-47-143	Roof C W Wall Center	ASSISSING BANKS		Parties AM AM				0.000000	50 ST
47	0227-47-144	Roof C W Wall Center	Black Seam Mastic	Misc.	Throughout Unit C Roof	NF	G	30 SF	7% Chrysotile	Category I ACM
	0227-47-145	Roof C N Wall Center	Mastro		Onne O Moor				Onlysouic	/ tolii
	0227-48-146	Roof C W Wall Center	Tan							
48	0227-48-147	Roof C N Wall Center	Tan Flashing	Misc.	Unit C Roof	NF	G	300 SF	None Detected	Non-ACM
	0227-48-148	Roof C S Wall Center	Caulking						Detected	
	0227-49-149	Roof C Center	Disale				8	X	8	
49	0227-49-150	Roof W Center	<ul><li>Black</li><li>Penetration</li></ul>	Misc.	Unit C Roof	NF	G	85 SF	None Detected	Non-ACM
	0227-49-151	Roof N Center	Mastic							
	0227-50-152	Roof C W Wall Center	74							
50	0227-50-153	Roof C Wall Center	Tan Penetration	Misc.	Unit C Roof	NF	G	10 SF	None Detected	Non-ACM
	0227-50-154	Roof N Wall Center	Mastic		K. 25 (1992) - C. 1992 - P. 1993	55.00		546550-1-0-44	Detected	
	0227-51-155	Roof C Center	·							
51	0227-51-156	Roof W Center	Black Roof Mastic	Misc.	Unit C Roof	NF	G	100 SF	None Detected	Non-ACM
	0227-51-157	Roof N Center	Waste						Detected	
	0227-52-158	Roof C W Wall S End	Off-White				8 8	S		
52	0227-52-159	Roof C W Wall S End	Seam	Misc.	Throughout Unit C Roof	NF	G	20 SF	2% Chrysotile	Category I ACM
	0227-52-160	Roof C W Wall S End	Mastic		Onit O Noor				Onlysouic	Nom
	0227-53-161	Roof C Tower NE	Black				S			
53	0227-53-162	Roof C Tower NE	Window	Misc.	Unit C Roof Tower	NF	G	120 SF	None Detected	Non-ACM
	0227-53-163	Roof C Tower NE	Sealant		Tower				Detected	
	0227-54-164	Roof C Tower NW	\A/bit=							
54	0227-54-165	Roof C Tower NW	White Window	Misc.	Unit C Roof	NF	G	15 SF	None Detected	Non-ACM
	0227-54-166	Roof C Tower NW	Caulking						Detection	
	0227-55-167	Roof C N Wall Center			- 1		1			
55	0227-55-168	Roof C N Wall Center	Gray Mortar	Misc.	Unit C Roof	NF	G	30 SF	None Detected	Non-ACM
	0227-55-169	Roof C N Wall Center	7						Detected	



	20000000000	T 27 92/21 2000/07			ı					r
	0227-56-170	Roof C Tower S Wall	Gray		Unit C Roof				None	
56	0227-56-171	Roof C Tower S Wall	Flashing Caulking	Misc.	Tower	NF	G	40 SF	Detected	Non-ACM
	0227-56-172	Roof C Tower W Wall		,			10	ē.		
	0227-57-173	Receiving/Discharge S Wall Center								
	0227-57-174	Processing Bathroom N Wall W End								
	0227-57-175	Library E Wall N End	White		Linit O				News	
57	0227-57-176	H.R. Manager E Wall N End	Drywall / Joint	Misc.	Unit C Interior	F	G	10,560 SF	None Detected	Non-ACM
	0227-57-177	H.R. Assistant E Wall Center	Compound							
	0227-57-178	Waiting E Wall Center	8							
	0227-57-179	H.R. Manager W Wall Center								
	0227-58-180	Receiving/Discharge Ceiling N	ý.							
58	0227-58-181	Receiving/Discharge Ceiling N	White 9"x9" Ceiling Tile	Misc.	Unit C Interior	F	G	1,700 SF	None Detected	Non-ACM
5 5	0227-58-182	Receiving/Discharge Ceiling N	. Herry sau Cartes		1510012500488328		2 %	×	To conduct to south	2
8	0227-59-183	Receiving/Discharge Ceiling N			11.01.0104.022.00000		3 3	X	AND	8 8
59	0227-59-184	Receiving/Discharge Ceiling N	Brown Puck Mastic	Misc.	Unit C Interior	NF	G	1,700 SF	None Detected	Non-ACM
	0227-59-185	Receiving/Discharge Ceiling N								
	0227-60-186	Counter E Wall Center	Black		100 March 201				9275	
60	0227-60-187	Counter E Wall Center	Window	Misc.	Unit C Interior	NF	G	1,250 SF	None Detected	Non-ACM
	0227-60-188	Sally Port S Wall Center	Caulking							
	0227-61-189	W Corridor S Wall Center	8							
61	0227-61-190	W Corridor S Wall Center	Tan Cove Base Mastic	Misc.	Unit C Interior	NF	G	1,900 SF	None Detected	Non-ACM
	0227-61-191	Witness/Attorney Room N Wall W End								
	0227-62-192	Tower E Center	Red 9"x9"							
62	0227-62-193	Witness/Attorney Room Center	Vinyl Floor	Misc.	Unit C Interior	NF	G	3,200 SF	None Detected	Non-ACM
	0227-62-194	Waiting S Center	Tile		entero Anna		g g g	6		
	0227-63-195	Witness/Attorney Room Center	and the second section of the		11 140 1100 275000				aucrostocyce	
63	0227-63-196	Witness/Attorney Room Center	White Vinyl Floor Tile	Misc.	Unit C Interior	NF	G	300 SF	None Detected	Non-ACM
	0227-63-197	Witness/Attorney Room Center								
	0227-64-198	H.R. Manager Center	E.				7			
64	0227-64-199	H.R. Assistant Center	Black Floor Mastic	Misc.	Unit C Interior	NF	G	3,500 SF	None Detected	Non-ACM
	0227-64-200	Tower Center E	( Marine Marine)		310,000 ASA					
	0227-65-201	Kitchen Center N		ľ			30 AC			×.
65	0227-65-202	Kitchen Center N	White 2'x4' Ceiling Tile	Misc.	Unit C Interior	F	G	2,200 SF	None Detected	Non-ACM
	0227-65-203	Kitchen Center N	Celling Tile		intenoi				Detected	
$\vdash$	0227-66-204	Kitchen W Wall S End								
66	0227-66-205	Tower S Wall E End	Red Electrical	Misc.	Unit C	NF	G	75 SF	None	Non-ACM
00	0227-66-206	Waiting N Wall W End	Mastic	WIISC.	Interior	IVI	G	1001	Detected	NOTACIVI
	STOREGOE WAS TO SECURE	NAME OF STREET			-					
	0227-67-207	Maintenance N Wall Center	į.							
	0227-67-208	Daily Stores N Wall Center	1,5000						2000	
67	0227-67-209	Kitchen E Wall Center	Gray Plaster	Misc.	Unit C Interior	E	G	4,200 SF	None Detected	Non-ACM
	0227-67-210	Staff Restroom E Wall Center								
	0227-67-211	Daily Stores S Wall W End								



					_					
	0227-68-212	Daily Stores Center	1 500 6000		300000000000				1000	
68	0227-68-213	Laundry Office Center	Tan Fire Proofing	TSI	Unit C Interior	F	G	200 SF	None Detected	Non-ACM
	0227-68-214	Maintenance Center	College Lot Balls		19 100 TO 100 Feb.					
	0227-69-215	Daily Stores Center N	Off Milete							ia ka
69	0227-69-216	Daily Stores Center N	Off-White Fire	TSI	Unit C Interior	F	G	850 SF	None Detected	Non-ACM
	0227-69-217	Daily Stores Center N	Insulation		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
	0227-70-218	Daily Stores E Wall N End	Off White		Throughout Unit C					
70	0227-70-219	Kitchen E Wall S End	Off-White Door Seam	Misc.	Interior	NF	G	700 SF	2% Chrysotile	Category I ACM
	0227-70-220	Kitchen S Wall Center	Mastic		Around All Doors				oyouo	,,,,,,,,
	0227-71-221	Loading Area Center					100			80
71	0227-71-222	Loading Area Center	Gray Concrete	Misc.	Unit C Interior	NF	G	13,500 SF	None Detected	Non-ACM
	0227-71-223	Loading Area Center								
	0227-72-224	Secretary SE			Unit C					
72	0227-72-225	Superintendent SE	Yellow Carpet Glue	Misc.	Interior	NF	G	1,200 SF	None Detected	Non-ACM
	0227-72-226	Case Worker NW			Offices					0 50
	0227-73-227	Kitchen Center N								80 NO
73	0227-73-228	Kitchen Center N	White 2'x4' Ceiling Tile	Misc.	Unit C Interior	F	G	1,700 SF	None Detected	Non-ACM
	0227-73-229	Kitchen Center N			HARRIS AND				- HELEGENERALI	
	0227-74-230	Boiler Room S Center	Black /		Within Unit					
74	0227-74-231	Boiler Room S Center	White Duct Seam	Misc.	C Interior on Rectangular	NF	G	250 SF	5% Chrysotile	Category I ACM
	0227-74-232	Boiler Room S Center	Mastic		HVAC Ducts				1.6	
	0227-75-233	Boiler Room E Wall Center								
75	0227-75-234	Boiler Room E Wall Center	Tan Cove Base Mastic	Misc.	Boiler Room Unit C	NF	G	20 SF	None Detected	Non-ACM
	0227-75-235	Boiler Room E Wall Center			10000000000000				14/90/00/00/00/00/00/00/00/00/00/00/00/00/	

#### Legend:

HA = Homogenous Material

N = North, E = East, W = West, S = South, SF = Square Feet, LF = Linear Feet, ND = None Detected Classification (Class.): Misc. = Miscellaneous, Surf. = Surfacing, TSI = Thermal System Insulation Condition: G = Good, D = Damaged, SD = Significantly Damaged Categories (Cat.):

- CalOSHA: ACCM = Asbestos Containing Construction Materials, ACM = Asbestos Containing Materials Class II, Class III, Class IV
   Presumed Asbestos Containing Material (PACM) = means thermal system insulation and surfacing material found in buildings constructed no later than 1980
- BAAQMD/NESHAPS: Cat I = Category I Non-friable ACM, Cat II = Category II Non-friable ACM, RACM = Regulated Asbestos Containing Materials

\*The locations and quantities provided are estimates based solely on accessible materials within the survey area. There may be additional locations and quantities of asbestos-containing materials present at the Subject Property.

\*\*In accordance with 40 CFR Section 61.141 and US EPA Applicability Determination Index Control Number: C112, if the amount by visual estimation appears to be less than 10 percent, the owner or operator may (1) assume the amount to be greater than 1 percent and treat the materials asbestos-containing material, or (2) require verification of the amount by point counting. If a result obtained by point count is different from a result obtained by visual estimation, the point count result will be used. Please note the Certified Asbestos Consultant will assume any material that is <1% analyzed via PLM and not verified by point count as an Asbestos Containing Material

The third-party laboratory will discard all submitted samples after thirty (30) calendar days following receipt of the samples. Any additional analysis must be requested within thirty (30) days by the Client.



## **ATTACHMENTS**



## **ATTACHMENT I**

LABORATORY ANALYTICAL REPORT(S)

(INCLUDING CHAIN OF CUSTODY FORMS)



Report for:

**EPK Tustin Titan Environmental Solutions, Inc.**1521 East Orangethorpe Ave, Ste B
Fullerton, CA 92831

Eurofins EPK Built Environment Testing, LLC

Project: 120316-AS, LM; 5701 8th street, Dublin, CA

EML ID: 3555513

Approved by:

Regarding:

Dates of Analysis: Asbestos PLM: 03-06-2024

EMLab ID: 3555513, Page 1 of 18

Danny Li

Approved Signatory

Service SOPs: Asbestos PLM (EPA 40CFR App E to Sub E of Part 763 & EPA METHOD 600/R-93-116, SOP EM-AS-S-1267) NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. The results relate only to the samples as received and tested. The results include an inherent uncertainty of measurement associated with estimating percentages by polarized light microscopy. Measurement uncertainty data for sample results with >1% asbestos concentration can be provided when requested.

Eurofins EPK Built Environment Testing, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Date of Sampling: 02-27-2024

Date of Receipt: 02-28-2024

Re: 120316-AS, LM; 5701 8th street, Dublin, CA

Date of Receipt: 02-28-2024

Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

**Total Samples Submitted:** 66 **Total Samples Analyzed:** 66

Lab ID-Version 1: 17385493-1

Lab ID-Version : 17385494-1

Lab ID-Version 1: 17385495-1

Lab ID-Version‡: 17385496-1

EMLab ID: 3555513, Page 2 of 18

Total Samples with Layer Asbestos Content > 1%: 0

#### Location: 0227-01 01, Roof B SW Corner, Black Penetration Mastic

Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Good

#### Location: 0227-01 02, Roof B NW Corner, Black Penetration Mastic

Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Good

#### Location: 0227-01 03, Roof B NE Corner, Black Penetration Mastic

Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Good

#### Location: 0227-02 04, Roof B South Corner, Grev Seam Mastic

Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 1: 17385498-1

Lab ID-Version 17385499-1

Lab ID-Version †: 17385500-1

EMLab ID: 3555513, Page 3 of 18

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-02 05, Roof B South Corner, Grev Seam Mastic

Location: 0227-02 05, Roof B South Corner, Grey Seam	Mastic Lab ID-Version‡: 17385497-1
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

Location: 0227-02 06, Roof B South E. End, Grey Seam Mastic

Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

Location: 0227-03 07, Roof B South W. End, Off-White Flashing Caulking

Sample Layers	Asbestos Content
Gray Roof Flashing Caulking	ND
Sample Composite Homogeneity:	Moderate

Location: 0227-03 08 Roof R West Center, Off-White Flashing Caulking

Location: 0227 03 00, Roof B West Center, On White I	asing Cauking
Sample Layers	Asbestos Content
Gray Roof Flashing Caulking	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version : 17385503-1

Lab ID-Version 17385504-1

EMLab ID: 3555513, Page 4 of 18

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 C/O: EPK Tustin Date of Receipt: 02-28-2024 Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-03 09, Roof B East N. End, Off-White Flashing Caulking

Location: 0227-03 09, Roof B East N. End, Off-White Fl	lashing Caulking Lab ID-Version‡: 17385501-1
Sample Layers	Asbestos Content
Gray Roof Flashing Caulking	ND
Sample Composite Homogeneity:	Moderate

#### Location: 0227-04 10, Roof B West Center, Off-White Exterior Wall Texture Lab ID-Version‡: 17385502-1

Sample Layers	Asbestos Content
Gray Cementitious Material Texture	ND
Blue Fibrous Material (Mesh)	ND
Composite Non-Asbestos Content:	10% Glass Fibers
Sample Composite Homogeneity:	Moderate

#### Location: 0227-04 11, Roof B NE Center, Off-White Exterior Wall Texture

Sample Layers	Asbestos Content
Gray Cementitious Material Texture	ND
Sample Composite Homogeneity:	Moderate

#### Location: 0227-04 12, Roof B East Center, Off-White Exterior Wall Texture

Sample Layers	Asbestos Content
Gray Cementitious Material Texture	ND
Blue Fibrous Material (Mesh)	ND
Composite Non-Asbestos Content:	10% Glass Fibers
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 1: 17385506-1

Lab ID-Version : 17385507-1

Lab ID-Version 1: 17385508-1

EMLab ID: 3555513, Page 5 of 18

Client: Titan Environmental Solutions, Inc. C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th street, Dublin, CA

Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-05 13, Roof B Center, Black Sealant

Location: 0227-05 13, Roof B Center, Black Sealant	Lab ID-Version‡: 17385505-1
Sample Layers	Asbestos Content
Black Sealant	ND
Sample Composite Homogeneity:	Moderate

#### Location: 0227-05 14, Roof B Center, Black Sealant

Sample Layers	Asbestos Content
Black Sealant	ND
Sample Composite Homogeneity:	Moderate

#### Location: 0227-05 15, Roof B Center, Black Sealant

Sample Layers	Asbestos Content
Black Sealant	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-06 16, Roof B NE Corner, Grev HVAC Mastic

Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 1: 17385510-1

Lab ID-Version : 17385511-1

Lab ID-Version 1: 17385512-1

EMLab ID: 3555513, Page 6 of 18

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

ASBESTOS PLM REPORT

Location: 0227-06 17, Roof B NE Corner, Grey HVAC Mastic

Location: 0227-06 17, Roof B NE Corner, Grey HVAC M	IasticLab ID-Version‡: 17385509-1
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity: Good	

Location: 0227-06 18, Roof B NE Corner, Grev HVAC Mastic

20000000 0227 00 10, 10001 2 112 0011101, G103 11 1110 11	The state of the s
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

Location: 0227-07 19, Roof B South Center, Black Roof Mastic

Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Mastic	ND
Composite Non-Asbestos Content: 15% Cellulose	
Sample Composite Homogeneity:	Moderate

Location: 0227-07 20, Roof B South Center, Black Roof Mastic

20000000 022. 0. 20,10002 200000 000001,20000 110002	
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
	5% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17385513-1

EMLab ID: 3555513, Page 7 of 18

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th street, Dublin, CA

Date of Sampling: 02-27-2024

Date of Receipt: 02-28-2024

Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-07 21, Roof B South Center, Black Roof Mastic

Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
	5% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-08 22, Unit B Shower 1 W. Wall, White Drywall (Joint Compound)

Lab ID-Version:: 17385514-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Peach Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-08 23, Unit B Shower 1 E. Wall, White Drywall (Joint Compound)

Lab ID-Version 1: 17385515-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Yellow Fibrous Material (Mesh)	ND
Peach Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	
	3% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-08 24, Unit B Shower 2 W. Wall, White Drywall (Joint Compound)

Lab ID-Version: 17385516-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Peach Drywall with Brown Paper	ND
<b>Composite Non-Asbestos Content:</b>	10% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17385517-1

Lab ID-Version‡: 17385518-1

Lab ID-Version‡: 17385519-1

Lab ID-Version 1: 17385520-1

EMLab ID: 3555513, Page 8 of 18

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th street, Dublin, CA

Date of Sampling: 02-27-2024

Date of Receipt: 02-28-2024

Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-09 25, 2nd Floor Corridor SW, White Ceiling 2' x 2'

Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose
_	25% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-09 26, 2nd Floor Corridor SW, White Ceiling 2' x 2'

g	
Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose
_	25% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-09 27, 2nd Floor Corridor SW, White Ceiling 2' x 2'

Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose
-	25% Glass Fibers
Sample Composite Homogeneity:	Moderate

#### Location: 0227-10 28, B211 W. Wall Center, Tan Cove Base Mastic

200W1011 V22. 10 20, 2211 VV VV WIN 201101, 1 WIN 20 V 2 WIN 17 WIN 20 V	
Sample Layers	Asbestos Content
Tan Mastic	ND
Black Mastic (Trace)	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 1: 17385522-1

Lab ID-Version‡: 17385523-1

EMLab ID: 3555513, Page 9 of 18

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

ASBESTOS PLM REPORT

Location: 0227-10 29, B237 N. Wall Center, Tan Cove Base Mastic

Location: 0227-10 29, B237 N. Wall Center, Tan Cove Ba	ase Mastic Lab ID-Version‡: 17385521-1
Sample Layers	Asbestos Content
Tan Mastic	ND
Sample Composite Homogeneity: (	Good

Location: 0227-10 30, B113 W. Wall Center, Tan Cove Base Mastic

Sample Layers	Asbestos Content
Tan Mastic	ND
Sample Composite Homogeneity:	Good

Location: 0227-11 31, B216 Floor Center, Grey Vinyl Floor Tile 9" x 9"

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 0227-11 32, B221 Floor Center, Grey Vinyl Floor Tile 9" x 9"

Location: 0227-11 32, B221 Floor Center, Grey Vinyl Fl	loor Tile 9" x 9" Lab ID-Version‡: 17385524-1
Sample Layers	Asbestos Content
Gray Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17385525-1

Lab ID-Version 1: 17385526-1

Lab ID-Version † 17385527-1

Lab ID-Version 1: 17385528-1

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th street, Dublin, CA

Date of Sampling: 02-27-2024

Date of Receipt: 02-28-2024

Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-11 33, B122 Floor Center, Grev Vinyl Floor Tile 9" x 9"

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity: Moderate	

### Location: 0227-12 34, 1st Floor Corridor SE, White Vinyl Floor Tile 9" x 9"

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic (Trace)	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-12 35, 1st Floor Corridor W Center, White Vinyl Floor Tile 9" x 9"

Education: 0227-1255, 1st Floor Corridor W Center, White Vinyr Floor The X	
Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic (Trace)	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-12 36, 1st Floor Corridor NE, White Vinyl Floor Tile 9" x 9"

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic (Trace)	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version : 17385530-1

Lab ID-Version 1: 17385531-1

Lab ID-Version‡: 17385532-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-13 37, B219 Floor Center, Black Floor Mastic

Location: 0227-13 37, B219 Floor Center, Black Floor M	lastic Lab ID-Version‡: 17385529-1
Sample Layers	Asbestos Content
Black Flooring Mastic	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-13 38, B121 Floor Center, Black Floor Mastic

Sample Layers	Asbestos Content
Black Flooring Mastic	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-13 39, B122 Floor Center, Black Floor Mastic

Sample Layers	Asbestos Content
Black Flooring Mastic	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-14 40, Shower 1 N. Wall Center, Grev Concrete

Sample Layers	Asbestos Content
Gray Concrete	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 17385533-1

Lab ID-Version 1: 17385534-1

Lab ID-Version 17385535-1

Lab ID-Version 17385536-1

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th street, Dublin, CA

Date of Sampling: 02-27-2024

Date of Receipt: 02-28-2024

Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-14 41, Shower 2 N. Wall Center, Grey Concrete

Sample Layers	Asbestos Content
Gray Concrete	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-14 42, Laundry S. Wall Center, Grey Concrete

Sample Layers	Asbestos Content
Gray Concrete	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-15 43, 1st Floor Corridor N. White Ceiling Tile 9" x 9"

	8
Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose
_	30% Glass Fibers
Sample Composite Homogeneity:	Moderate

#### Location: 0227-15 44, 1st Floor Corridor N. White Ceiling Tile 9" x 9"

Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose 30% Glass Fibers
Sample Composite Homogeneity:	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17385538-1

Lab ID-Version 1: 17385539-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-15 45, 1st Floor Corridor N. White Ceiling Tile 9" x 9"

Location: 0227-15 45, 1st Floor Corridor N. White Ceilin	ng Tile 9" x 9" Lab ID-Version‡: 17385537-1
Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose
	30% Glass Fibers
Sample Composite Homogeneity:	Moderate

#### Location: 0227-16 46, Shower 1 N. Wall Center, Grey Plaster

Sample Layers	Asbestos Content
Gray Plaster	ND
White Plaster	ND
Off-White Plaster	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-16 47. Shower 2 N. Wall Center, Grev Plaster

Sample Layers	Asbestos Content
Gray Plaster	ND
White Plaster	ND
Off-White Plaster (Trace)	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-16 48, Sanitor E. Wall Center, Grey Plaster

Location: 0227-16 48, Sanitor E. Wall Center, Grey Plas	<b>Ster</b> Lab ID-Version‡: 17385540-1
Sample Layers	Asbestos Content
Gray Plaster	ND
White Plaster	ND
Off-White Plaster	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17385542-1

Lab ID-Version‡: 17385543-1

Lab ID-Version †: 17385544-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-17 49, Laundry S. Wall Center, White Pipe Insulation

Location: 0227-17 49, Laundry S. Wall Center, White P	<b>Tipe Insulation</b> Lab ID-Version‡: 17385541-1
Sample Layers	Asbestos Content
Silver Foil	ND
Cream Paper	ND
Yellow Insulation	ND
Composite Non-Asbestos Content:	75% Glass Fibers 10% Cellulose
Sample Composite Homogeneity:	Moderate

#### Location: 0227-17 50, Laundry S. Wall Center, White Pipe Insulation

Sample Layers	Asbestos Content
Silver Foil	ND
Cream Paper	ND
Yellow Insulation	ND
Composite Non-Asbestos Content:	
	10% Cellulose
Sample Composite Homogeneity:	Moderate

## Location: 0227-17 51, Laundry S. Wall Center, White Pipe Insulation

Sample Layers	Asbestos Content
Silver Foil	ND
Cream Paper	ND
Yellow Insulation	ND
Composite Non-Asbestos Content:	
	10% Cellulose
Sample Composite Homogeneity:	Moderate

#### Location: 0227-18 52, 1st Floor Corridor N. Brown Door Mastic

Location: 0227-10 32, 1st 11001 Corridor 11, Brown Door	TVIASTIC End ID Version 4. 175055 11 1
Sample Layers	Asbestos Content
Brown Mastic	ND
Gray Fibrous Material	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17385545-1

Lab ID-Version‡: 17385546-1

Lab ID-Version‡: 17385547-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-18 53, 1st Floor Corridor N, Brown Door Mastic

, , ,	
Sample Layers	Asbestos Content
White Compound	ND
Brown Mastic	ND
Gray Fibrous Material	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

#### Location: 0227-18 54, 1st Floor Corridor N, Brown Door Mastic

Sample Layers	Asbestos Content
White Compound	ND
Brown Mastic	ND
Gray Fibrous Material	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

## Location: 0227-19 55, Laundry S. Center, Tan HVAC Duct Mastic

Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

## Location: 0227-19 56, Laundry S. Center, Tan HVAC Duct Mastic

Location: 0227-19 56, Laundry S. Center, Tan HVAC I	Ouct Mastic Lab ID-Version‡: 17385548-1
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 1: 17385550-1

Lab ID-Version 1: 17385551-1

Lab ID-Version 1: 17385552-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-19 57, Laundry S. Center, Tan HVAC Duct Mastic

Location: 0227-19 57, Laundry S. Center, Tan HVAC Du	ict Mastic Lab ID-Version‡: 17385549-1
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity: (	Good

Location: 0227-20 58, B141 Cell Door, Black Cell Window Caulking

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

Location: 0227-20 59, B139 Cell Door, Black Cell Window Caulking

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

Location: 0227-20 60, B117 Cell Door, Black Cell Window Caulking

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th street, Dublin, CA

Date of Sampling: 02-27-2024

Date of Receipt: 02-28-2024

Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-21 61, 1st Floor Corridor West Wall N. End, Red Electrical Mastic Lab ID-Version:: 17385553-1

Sample Layers	Asbestos Content
Red Mastic	ND
Composite Non-Asbestos Content:	10% Glass Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-21 62, 1st Floor Corridor West Wall N. End, Red Electrical Mastic Lab ID-Version‡: 17385554-1

Sample Layers	Asbestos Content
Red Mastic	ND
Composite Non-Asbestos Content:	10% Glass Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-21 63, 1st Floor Corridor West Wall N. End, Red Electrical Mastic Lab ID-Version 1: 17385555-1

Sample Layers	Asbestos Content
Red Mastic	ND
Composite Non-Asbestos Content:	10% Glass Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-22 64, Roof B SW, Black Round Roof System

Sample Layers	Asbestos Content
Gray Roofing Material	ND
Gray Roofing Felt	ND
Gray Roofing Material	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Content:	20% Glass Fibers
	15% Synthetic Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $\ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Lab ID-Version 1: 17385556-1

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17385557-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-27-2024 Date of Receipt: 02-28-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th street, Dublin, CA Date of Report: 03-06-2024

#### ASBESTOS PLM REPORT

Location: 0227-22 65, Roof B NW, Black Round Roof System

Sample Layers	Asbestos Content
Gray Roofing Material	ND
Gray Roofing Felt	ND
White Roofing Material	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Composite Non-Asbestos Content:	20% Glass Fibers 10% Synthetic Fibers
Sample Composite Homogeneity:	

Location: 0227-22 66, Roof B E Center, Black Round R	oof System Lab ID-Version‡: 17385558-1
Sample Layers	Asbestos Content
Gray Roofing Felt	ND
White Roofing Material	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Composite Non-Asbestos Content:	
	10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Filed 04/05/24 Page 42 of 125 Species Chain of Custody Case 4:23-cv-04155-YGR Document 246-2 Special Instructions:  $\hfill\Box$  Analyze all wall system samples; Stop at first positive (>1%) for all FEDERAL CORRECTIONAL ENSTITUTION -Project Name:



Project No.:

Inspector:

Sample Date:

Send Results to:

Project Address:

DUBLIN CAMP, UNITS K. B. 5701 STH STREET, DUBLINGA

C PETENTIEN single layer, homogenous materials (D)

CENTER- Stop at first positive (>1%) for ALL wall system samples and/or single layer, homogenous materials (G)

94568 GABRIEL KLEIN

□ Analyze ALL samples.

□ Other:

02.27.24 RESULTS NORCAL@TITAN-ENVIRO.COM TAT: 3 hr / 6 hr / 24 hr / Other: 5 Day

S.Occupied □Unoccupied

10101101		Analysis:		Material Description		Material Locations	Quant
Sample Number			ple Location				755F
0227.01	01	ROUF B S	SW CORNER	BLACK PENETRATION MASTIC	QUOF	<i>b</i>	(*)
	02	ROOF B K	UN CORNER	Material			1
		RUCF B N		Texture/Pattern			
				Assembly/Layers			
				Friable Non-Friable			003555513
				TSI / Surf / Misc			
				Condition: G / D / SD			
0227.02 04	04	ROOFB 50	UTH CENTER	GARY SEAM MASTIC	Roct	8	305F
Opera		ALL THE REAL PROPERTY AND ADDRESS OF THE PERSON OF THE PER	It CENTER	Material			
		ect B SM		Testure/Pattern			
	00	eur o	505,50H - 505 - 100,00H - 5500.	Assenstity/Layers			
				Friable / Non-Friable			
	_			TSI / Surf / Miss.			
				Condition: G / D / SD			
0227.03	07	OXFR =	outh with	OFF-WHITE FLASHING COULKING	ROUT	B	260
0601.05	08		EST CENTER	Material			
	09		3T. NJ. END	Texture/Pattern			
	0-7	1	5. 10.5.5	Assembly/Lavers			
	-			Friable / Non-Friable			
				TSI / Surf / Misc			
	-	-		Condition: G V D / SD			

Relinquished: (sign):	de
Received by Lab (sign):	

Name (print): GOBKIEL, KLEIN Name (print):

Date/Time: 02-27-24 Date/Time:

✓ Secure Dropbox ☐ Secure Courier Service

OAKLAND ADDRESS: 1901 HARRISON STREET, SUITE 100, OAKLAND, CA 94612 \* PHONE: 888-948-4826

Sample Nu	mber	Sample Loc	ation	Material Description	Material Locations	Quantity
	10	POOF B WEST O		OFF-WHITE EXTERNIBLE WALL TEXTURE	ROUT B PARAPET UDIC	780SF
2001.01	11		ANTH_	Material		
	12	EAST C		Texture/Pattern		
	10	P (A)		Assembly/Layers		
				Friable Non-Friable	0039	555513
				TSI / Surf / Misc.		
				Condition: G / D / SD		
	. 12	RUF B CENTE	R	BLACK SEALANT	RUOF B SKYLIGHT	855F
227-05	13	1		Material		
	14			Texture/Pattern		
	15	b 1		Assembly/Layers		
				Friable / Non-Friable		
				TSI / Surf / Misco		
				Condition: G / D / SD		
		ROOF B NE CO	PANFO	ency HUBC MISTIE	RUUT B HVAC SYSTEM	705F
0227.06	16	1	)	Material Material		
	17			Texture/Pattern		
	18	6 6	D	Assembly/Layers		
	_			Friable / Non-Friable		
				TSI / Surf / Misc.		
				Condition G / D / SD		

Sample Numb	er Sample Location	Material Description	Material Locations	Quantity
-	Stre/Calore	ROUT B	1305F	
/	1	Material		
20		Texture/Pattern		
2	& CENTER	Assembly/Layers	Million .	Warnerous ou
		Friable / Non-Friable		
		TSI / Surf / Misc	0035	555513
		Condition: G / D / SD		
0227.08 22	UNITE SHOUTER 1 W. WALL	WHERE DRYWALL 158924 COMPUND	GRIT B INTERIOR	97558
		Material		
2	V V	Texture/Pattern		
	CALL S STATE OF THE STATE OF TH	/ssembly/Layers		
		Friable / Non-Friable		
		TSI / Surf / Misco		
		Condition: G / D / SD		
0227.09 2	2ND FLOOR CORRIDOR SU	) - WHITE CEILINGS THE 2XZ	CNIT B INTERIOR	1,2005
2	/ / /	Material		
2		Texture/Pattern		
		Assembly/Layers		
		Friable / Non-Friable		
		TSI / Surf / Misc.		
		Condition: G D / SD		

# 

Sample No	umbor	Sample Location	Material Description	Material Locations	Quantity
-	28	B211 W. WALL CEASTER	THE COVERAGE WASTIC	ONIT B INTERIOR	1,1005*
5227.10			Material		
		B113 W. WALL CENTER	Texture/Paxtern		N.
	30	BIIO W. WALL CEPILE	Assembly/Layers		
			Friable / Non-Friable		003555513
			TSI / Surf / Mise?		00333371
			Condition: G / D / SD		
	e 1	6216 FLOOR CENTER	GREY VINGL STEDBOR THE	UNITE INTERIOR	5,840SF
	32	BON FLUCK CENTER	g-spigar		
	33	BIZZ FLOOR CENTER	Texture/Pattern		
	22	13100	Assembly/Layers		
	-		Friable / (Non-Friable)		
	-		TSI / Surf / Misg.		
	+		Condition: G // D / SD		
0227.12	34	1 ST PLUOR CURPIPOR SE	WHITE VINGLE FOURT THE	UNIT B INTERIOR	530SF
000000	35	The second secon	- danish du		
	36		Texture/Pattorn		
	20		Assembly/Layers		
			Friable / Non-Friable		
-			TSI / Surf / Misc		
			Condition: G / D / SD		

Sample Number	er Sample Location	Material Description	Material Locations	Quantity
0227-13 37	BZIQ FLOOR CENTER	BLACK FLUSTIC MASTIC	UNIT B INTERIOR	6,370SF
38	i i i i i i i i i i i i i i i i i i i	Material		
39		Texture/Pattern		
-		Assembly/Layers		
		Friable / Non-Friable	00355	5513 —
		TSI / Surf / Misc.	00333	
		Condition: G // D / SD		
0227-14 40	SHOWER I N. WALL CENTER	GREY CONCRETE	LNIT BINTERIUR	12,000
41	to the stand	Material		
42	Activity and a second	Texture/Pattern		
7.2		Assembly/Layers		
		Friable / Non-Friable		
		TSI / Surf / Misc.		
		Condition G / D / SD		
0227.19 45	1SF FLOOR CORRIDOR N.	WHITE CEILING 1990E 9x9"	UNITE INTERIOR	220SF
44	1	Material		
47		Texture/Pattern		
4		Assembly/Layers		
		Friable / Non-Friable		
		TSI / Surf / Misco		
		Condition: G / D / SD		

# Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 47 of 125 Asbestos Chain of Custouy

Sample Number	er Sample Location	Material Description	Material Locations	Quantity
0227.16 46	and the second s	GREY PLASTE Welcolor	UNIT B INTERIOR	980SF
47	SHOWER 2 N. WALL CENTER	Material		
47		Texture/Pattern		
H (	, <del>-</del>	Assembly/Layers		
		Friable / Non-Friable		003555513
		TSI / Surf / Misc.		1
		Condition: G D / SD		
0227.17 49	LAUNDAY S. WALL CENTER	- WHITE PIPE INSURPRION	4NITB CAUNDAY	60 SF
90		Material		
51		Texture/Pattern		
	P P D	Assembly/Layers		
		Friable / Non-Friable		
		TST / Surf / Misc.		
		Condition: G / D / SD		
0227.18 52	15T FLOOD CORRIDOR N	BROWN PUERCOOMASTIC	UNIT & INTERIOR	Z205F
53		Material		
54		Texture/Pattern		
		Assembly/Layers		
		Friable / Non-Friable		
		TSI / Surf / Misc.		
		Condition: G / D / SD		

Sample No	ımher	Sample Location	Material Description	Material Location	
0227-19	55	LAUNDAY S. CENTER	TAN HUAC DEPOTO MASTIC	UNIT B LAULDY	HOSE
022(17)	56	LAURING S.	Material		
	57		Texture/Pattern		
	77	4 4	Assembly/Layers		
			Friable / (Non-Friable)		003555513
			TSI / Surf / Misc.		
			Condition: G / D / SD		
0227.20	58	BIHI CELL DUOR	BLACK CELL WYDOUW CALLEING	LNIT B INTERIOR	1705F
010(.00	59	B139 CELL DUOR	Material		
	-	BIT COL DOOR	Texture/Pattern		
	60	Dill car per	Assembly/Layers		
	-		Friable / Non-Friable		
	-		TSI / Surf / Misc		
	-		Condition G D / SD		
0227.21	61	1 ST PLACE CORRIDOR SIN	DED ELECTRICA COLOR MASTIC	UNIT BINTERIOR	205F
OLLIZI		WEST WALL NEND	Material		
	62		Texture/Pattern		
	60	b b	Assembly/Layers		
	+-		Friable / (Non-Friable		
	-		TSI / Surf / Misc		
	+		Condition: G / D / SD		

## Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 49 of 125Asbestos Chain of Custody

Sample Numb	er	Sample Location	Material Description	Material Location	
n27:22 64		SW	BLACK ROLLE BURGET SYSTEM	ROOF B	12,000SF
4		NW	Material		
66		E. CENTER	Texture/Pattern		
	- V		Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		003555513
	_		Condition: G // D / SD		
			Size/Color		
			Material		
			Texture/Pattern		
			Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		
			Size/Color		
			Material		
			Texture/Pattern		
			Assembly/Luyers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		



Report for:

**EPK Tustin Titan Environmental Solutions, Inc.**1521 East Orangethorpe Ave, Ste B
Fullerton, CA 92831

Regarding:

Eurofins EPK Built Environment Testing, LLC Project: 120316-AS, LM; 5701 8th St. Dublin CA

EML ID: 3557600

Approved by:

Dates of Analysis: Asbestos PLM: 03-07-2024

Approved Signatory Danny Li

Service SOPs: Asbestos PLM (EPA 40CFR App E to Sub E of Part 763 & EPA METHOD 600/R-93-116, SOP EM-AS-S-1267) NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. The results relate only to the samples as received and tested. The results include an inherent uncertainty of measurement associated with estimating percentages by polarized light microscopy. Measurement uncertainty data for sample results with >1% asbestos concentration can be provided when requested.

Eurofins EPK Built Environment Testing, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

EMLab ID: 3557600, Page 1 of 20

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024 Date of Receipt: 02-29-2024 Date of Report: 03-07-2024

#### **ASBESTOS PLM REPORT**

**Total Samples Submitted:** 70 **Total Samples Analyzed:** 70

Lab ID-Version 1: 17394823-1

Lab ID-Version : 17394824-1

Lab ID-Version 1: 17394825-1

Lab ID-Version‡: 17394826-1

EMLab ID: 3557600, Page 2 of 20

Total Samples with Layer Asbestos Content > 1%: 0

#### Location: 0227-23-67, Unit A Roof Center - Black Penetration Mastic

Edetation val. 20 07, emeritation center Butter times	The state of the s
Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

#### Location: 0227-23-68, Unit A Roof Center - Black Penetration Mastic

Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

#### Location: 0227-23-69, Unit A Roof Center - Black Penetration Mastic

Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

## Location: 0227-24-70, Unit A Roof Center - Black Sealant

Sample Layers	Asbestos Content		
Black Sealant	ND		
Sample Composite Homogeneity: Moderate			

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 1: 17394828-1

Lab ID-Version 1: 17394829-1

EMLab ID: 3557600, Page 3 of 20

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 C/O: EPK Tustin

Date of Receipt: 02-29-2024 Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-24-71, Unit A Roof Center - Black Sealant

Location: 0227-24-71, Unit A Roof Center - Black Seala	<b>nt</b> Lab ID-Version‡: 17394827-1
Sample Layers	Asbestos Content
Black Sealant	ND
Sample Composite Homogeneity:	Moderate

#### Location: 0227-24-72, Unit A Roof Center - Black Sealant

Sample Layers	Asbestos Content
Black Sealant	ND
Sample Composite Homogeneity:	Moderate

#### Location: 0227-25-73, Unit A Roof W. Center - HVAC Mastic Grey

Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-25-74. Unit A Roof W. Center - HVAC Mastic Grev

Location: 0227-25-74, Unit A Roof W. Center - HVAC	Mastic Grey Lab ID-Version‡: 17394830
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version : 17394832-1

Lab ID-Version : 17394833-1

EMLab ID: 3557600, Page 4 of 20

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 Date of Receipt: 02-29-2024 C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-25-75, Unit A Roof W. Center - HVAC Mastic Grey

Location: 0227-25-75, Unit A Roof W. Center - HVAC M	Iastic GreyLab ID-Version‡: 17394831-1
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity: (	Good

#### Location: 0227-26-76, Unit A Roof E. Center - Black Roof Mastic

Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose 5% Synthetic Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-26-77, Unit A Roof Center - Black Roof Mastic

Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose 5% Synthetic Fibers
Sample Composite Homogeneity:	

#### Location: 0227-26-78. Unit A Roof Center - Black Roof Mastic

Location: 0227-26-78, Unit A Roof Center - Black Roof	Mastic Lab ID-Version‡: 17394834-1
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
_	5% Synthetic Fibers
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version † 17394835-1

Lab ID-Version 1: 17394837-1

Lab ID-Version : 17394838-1

EMLab ID: 3557600, Page 5 of 20

Client: Titan Environmental Solutions, Inc. C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024 Date of Receipt: 02-29-2024 Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-27-79, Unit A Roof S. Wall Center - Wall Texture Off-White

Decation: 0227-27-7), Chit A Root S. Wan Center - Wan Texture On-White	
Sample Layers	Asbestos Content
Gray/White Cementitious Material Wall Texture	ND
Blue Fibrous Material (Mesh)	ND
Composite Non-Asbestos Content:	5% Glass Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-27-80. Unit A Roof S. Wall W. End- Wall Texture Off-White

Location: 0227-27-80, Unit A Roof S. Wall W. End- Wall Texture Off-White  Lab ID-Version: 1739		rsion‡: 17394836-1
Sample Layers	Asbestos Content	
Gray/White Cementitious Material Wall Texture	ND	
Blue Fibrous Material (Mesh)	ND	
Composite Non-Asbestos Content: 5% Glass Fibers		
Sample Composite Homogeneity:	Good	

## Location: 0227-27-81, Unit A Roof N. Wall Center - Wall Texture Off-White

Zocationi ozz. Z. or, emeri ricorri, van center va	Tenture on ville
Sample Layers	Asbestos Content
Gray/White Cementitious Material Wall Texture	ND
Blue Fibrous Material (Mesh)	ND
Composite Non-Asbestos Content:	5% Glass Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-28-82. Unit A Roof E. Wall S. End - Tan Flashing Caulking

20000000 022. 20 02) 0000111100120 1000120 1000111000120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 10001111001120 1000111001120 10001111001120 1000111001120 1000111001120 1000111001110011100111001110011100111001110011100111001110011100111000110001100011000110001100011000110001100011000110000	
Sample Layers	Asbestos Content
Gray Roof Flashing Caulking	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 17394842-1

EMLab ID: 3557600, Page 6 of 20

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 Date of Receipt: 02-29-2024 C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-28-83, Unit A Roof S. Wall Center - Tan Flashing Caulking

Location: 0227-28-83, Unit A Roof S. Wall Center - Tan	Flashing Caulking Lab ID-Version‡: 17394839-1
Sample Layers	Asbestos Content
Gray Roof Flashing Caulking	ND
Sample Composite Homogeneity:	Good

Location: 0227-28-84, Unit A Roof W. Wall Center - Tan Flashing Caulking Lab ID-Version : 17394840-1

Sample Layers	Asbestos Content
Gray Roof Flashing Caulking	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-29-85, Unit A Roof Center - Rolled Roof System Black

Location: 0227-29-85, Unit A Roof Center - Rolled Roof	System Black Lab ID-Version‡: 17394841-1
Sample Layers	Asbestos Content
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt	ND
Gray Roofing Material	ND
Gray Roofing Felt	ND
Composite Non-Asbestos Content:	10% Glass Fibers
	10% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

#### Location: 0227-29-86, Unit A Roof Center - Rolled Roof System Black

Sample Layers	Asbestos Content
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Gray Roofing Felt	ND
Composite Non-Asbestos Content:	
	10% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version : 17394843-1

EMLab ID: 3557600, Page 7 of 20

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024

Date of Receipt: 02-29-2024

Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-29-87, Unit A Roof Center - Rolled Roof System Black

Sample Layers	Asbestos Content
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Gray Roofing Material	ND
White Roofing Material	ND
Composite Non-Asbestos Content:	10% Glass Fibers 10% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-30-88, Shower 1 S. Wall Center - White Drywall/Joint Compound

Lab ID-Version 1: 17394844-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Yellow Fibrous Material (Mesh)	ND
Tan Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	
	5% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-30-89, Shower 1 S. Wall Center - White Drywall/Joint Compound

Lab ID-Version:: 17394845-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Yellow Fibrous Material (Mesh)	ND
Tan Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	10% Cellulose
_	5% Glass Fibers
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

## **Eurofins EPK Built Environment Testing, LLC**

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

EMLab ID: 3557600, Page 8 of 20

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024

Date of Receipt: 02-29-2024

Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-30-90, Shower 1 N. Wall Center - White Drywall/Joint Compound

Lab ID-Version 17394846-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Yellow Fibrous Material (Mesh)	ND
Tan Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	10% Cellulose 5% Glass Fibers
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

EMLab ID: 3557600, Page 9 of 20

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024

Date of Receipt: 02-29-2024

Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-30-91, Shower 1 N. Wall Center - White Drywall/Joint Compound

Lab ID-Version 17394847-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Yellow Fibrous Material (Mesh)	ND
Tan Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	
	5% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-30-92, Shower 2 N. Wall Center - White Drywall/Joint Compound

Lab ID-Version 1: 17394848-1

Sample Layers	Asbestos Content
White Joint Compound with Paint	ND
Yellow Fibrous Material (Mesh)	ND
Tan Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	
	5% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 0227-31-93, 2nd Floor S. Corridor E. End - White Ceiling Tile 2x2

Lab ID-Version: 17394849-1

Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	
	25% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 0227-31-94, 2nd Floor S. Corridor E. End - White Ceiling Tile 2x2

Lab ID-Version: 17394850-1

Asbestos Content
ND
0% Cellulose
5% Glass Fibers ood
59

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version\*: 17394851-1

Lab ID-Version 1: 17394853-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 C/O: EPK Tustin

Date of Receipt: 02-29-2024 Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-31-95 2nd Floor N. Corridor E. End. White Ceiling Tile 2x2

Education: 0227-31-93, 2nd Floor 14. Corridor E. End - White Centing The 2x2	
Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose
_	25% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 0227-32-96, 1st Floor Dayroom SE - Tan Based	cove Mastic Lab ID-Version‡: 17394852-1
Sample Layers	Asbestos Content
Tan Mastic	ND
Black Non-Fibrous Material (Trace)	ND
White Compound	ND
Sample Composite Homogeneity:	Moderate

Location: 0227-32-97, 1st Floor Dayroom SE - Tan Basecove Mastic

Sample Layers	Asbestos Content
Tan Mastic	ND
Black Non-Fibrous Material	ND
White Compound	ND
Sample Composite Homogeneity:	Moderate

Location: 0227-32-98, 1st Floor Dayroom NW - Tan Basecove Mastic

Location: 0227-32-98, 1st Floor Dayroom NW - Tan Bas	ecove Mastic Lab ID-Version‡: 17394854-1
Sample Layers	Asbestos Content
Tan Mastic	ND
Black Non-Fibrous Material (Trace)	ND
White Compound	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17394855-1

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024

Date of Receipt: 02-29-2024

Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-33-99, A140 Floor Center - Green Vinyl Floor Tile 9"x9"

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-33-100, N. Corridor Floor W. End - Green Vinyl Floor Tile 9"x9" Lab ID-Version‡: 17394856-1

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-33-101, S. Corridor Floor W. End - Green Vinyl Floor Tile 9"x9" Lab ID-Version‡: 17394857-1

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Black Mastic	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-34-102, N. Corridor Floor Center - White Vinyl Floor Tile 9"x9" Lab ID-Version‡: 17394858-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Gray Mastic	ND
Gray Compound	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 C/O: EPK Tustin Date of Receipt: 02-29-2024 Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-34-103, W. Corridor Floor S. End - White Vinyl Floor Tile 9"x9"

Lau ID- version <sub>4</sub> . 17394639-1	
tos Content	
ND	
ND	

Black/Yellow Mastic		
Sample Composite Homogeneity	Moderate	

Sample Layers White Floor Tile

Location: 0227-34-104, Dayroom Floor Center - White Vinyl Floor Tile 9"x9"

Lab ID-Version 1: 17394860-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Black/Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 0227-35-105, A138 Floor Center - Blue Vinyl Floor Tile 9"x9"

Lab ID-Version 1: 17394861-1

Sample Layers	Asbestos Content
Blue Floor Tile	ND
Black/Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 0227-35-106, A138 Floor Center - Blue Vinyl Floor Tile 9"x9"

Lab ID-Version 17394862-1

Sample Layers	Asbestos Content
Blue Floor Tile	ND
Black/Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17394863-1

Lab ID-Version 1: 17394864-1

Lab ID-Version 17394865-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 Date of Receipt: 02-29-2024 C/O: EPK Tustin Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-35-107, A138 Floor Center - Blue Vinvl Floor Tile 9"x9"

Sample Layers	Asbestos Content
Blue Floor Tile	ND
Black/Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

#### Location: 0227-36-108, A117 Floor Center - Black Floor Mastic

Sample Layers	Asbestos Content
Black Flooring Mastic	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-36-109, A120 Floor Center - Black Floor Mastic

Sample Layers	Asbestos Content
Black Flooring Mastic	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-36-110, A121 Floor Center - Black Floor Mastic

Location: 0227-36-110, A121 Floor Center - Black Floor	r Mastic Lab ID-Version‡: 17394866-1
Sample Layers	Asbestos Content
Black Flooring Mastic	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version 1: 17394868-1

Lab ID-Version 17394869-1

Lab ID-Version‡: 17394870-1

Client: Titan Environmental Solutions, Inc. C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024 Date of Receipt: 02-29-2024 Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-37-111, Laundry E. Wall Center - Grey Concrete

Location: 0227-37-111, Laundry E. Wall Center - Grey C	Concrete Lab ID-Version‡: 17394867-1
Sample Layers	Asbestos Content
Gray Concrete	ND
Sample Composite Homogeneity: (	Good

Location: 0227-37-112, Laundry E. Wall Center - Grey Concrete

Sample Layers	Asbestos Content
Gray Concrete	ND
Sample Composite Homogeneity:	Good

Location: 0227-37-113, Laundry E. Wall Center - Grey Concrete

Sample Layers	Asbestos Content
Gray Concrete	ND
Sample Composite Homogeneity:	Good

Location: 0227-38-114, W. Corridor Ceiling Center - White Ceiling Tile 9"x9"

Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	40% Cellulose
_	30% Glass Fibers
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

Date of Sampling: 02-28-2024

Date of Receipt: 02-29-2024

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Reccipt. 02-27-2024

Date of Report: 03-07-2024

Composite Non-Asbestos Content: 40% Cellulose

#### ASBESTOS PLM REPORT

Location: 0227-38-115, W. Corridor Ceiling Center - White Ceiling Tile 9"x9"

Х9 <sup></sup>	<b>9</b> Lab ID-Version‡: 1/3948/1-1	
Asbestos Co	ontent	
ND		

-	30% Glass Fibers
Sample Composite Homogeneity:	Good

Sample Layers

White Ceiling Tile

Location: 0227-38-116, W. Corridor Ceiling Center - White Ceiling Tile 9"x9"

Lab ID-Version‡: 17394872-1

Sample Layers	Asbestos Content
White Ceiling Tile	ND
Composite Non-Asbestos Content:	
	30% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 0227-39-117, W. Corridor Ceiling Center - Brown Puck Mastic

Lab ID-Version‡: 17394873-1

Sample Layers	Asbestos Content	
Brown Mastic	ND	
Gray Fibrous Material	ND	
Composite Non-Asbestos Content: 20% Cellulose		
Sample Composite Homogeneity:	Moderate	

#### Location: 0227-39-118, W. Corridor Ceiling Center - Brown Puck Mastic

Lab ID-Version‡: 17394874-1

Sample Layers	Asbestos Content
Brown Mastic	ND
Gray Fibrous Material	ND
Composite Non-Asbestos Content: 20% Cellulose	
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version : 17394876-1

Lab ID-Version 17394877-1

Lab ID-Version 1: 17394878-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 C/O: EPK Tustin

Date of Receipt: 02-29-2024 Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-39-119. W. Corridor Ceiling Center - Brown Puck Mastic

Location: 0227-39-119, W. Corridor Ceiling Center - Br	rown Puck Mastic Lab ID-Version‡: 17394875-1
Sample Layers	Asbestos Content
Brown Mastic	ND
Gray Fibrous Material	ND
Composite Non-Asbestos Content: 20% Cellulose	
Sample Composite Homogeneity:	Moderate

Location: 0227-40-120, Shower 2 N. Wall Center - Grev Plaster

Sample Layers	Asbestos Content
White Skim Coat	ND
Gray Plaster	ND
Sample Composite Homogeneity: Moderate	

Location: 0227-40-121, Shower 2 S. Wall Center - Grey Plaster

Sample Layers	Asbestos Content
White Skim Coat	ND
Gray Plaster	ND
Sample Composite Homogeneity:	Moderate

Location: 0227-40-122, Shower 1 N. Wall Center - Grey Plaster

Sample Layers	Asbestos Content
White Skim Coat	ND
Gray Plaster	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17394879-1

Lab ID-Version 1: 17394880-1

Lab ID-Version : 17394881-1

Lab ID-Version‡: 17394882-1

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024

Date of Receipt: 02-29-2024

Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-40-123, Shower 1 S. Wall Center - Grev Plaster

Sample Layers	Asbestos Content
White Skim Coat	ND
Gray Plaster	ND
Sample Composite Homogeneity: Moderate	

Location: 0227-40-124, A138 E. Wall S. End - Grey Plaster

Education descripting and in the state of th	···
Sample Layers	Asbestos Content
White Skim Coat	ND
Gray Plaster	ND
Sample Composite Homogeneity: Moderate	

Location: 0227-41-125, Laundry NE Corner - White Pipe Insulation

Sample Layers	Asbestos Content
White Paper	ND
Silver Foil	ND
Yellow Insulation	ND
Composite Non-Asbestos Content:	80% Glass Fibers
_	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-41-126, Laundry NE Corner - White Pipe Insulation

Sample Layers	Asbestos Content
White Paper	ND
Silver Foil	ND
Yellow Insulation	ND
Composite Non-Asbestos Content:	80% Glass Fibers
	10% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17394883-1

Lab ID-Version 17394884-1

Lab ID-Version 1: 17394885-1

Lab ID-Version\*: 17394886-1

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St. Dublin CA

Date of Sampling: 02-28-2024

Date of Receipt: 02-29-2024

Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-41-127, Laundry NE Corner - White Pipe Insulation

Sample Layers	Asbestos Content
White Paper	ND
Silver Foil	ND
Yellow Insulation	ND
Composite Non-Asbestos Content:	80% Glass Fibers 10% Cellulose
Sample Composite Homogeneity:	

Location: 0227-42-128, Laundry SE Corner - Tan HVAC Mastic

Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

Location: 0227-42-129, Laundry SE Corner - Tan HVAC Mastic

	2 1.200 020
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

Location: 0227-42-130, Laundry SE Corner - Tan HVAC Mastic

Location: 0227-42-130, Launury SE Corner - Tan II VA	C Wastic
Sample Layers	Asbestos Content
Gray Mastic	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version †: 17394887-1

Lab ID-Version 17394888-1

Lab ID-Version 1: 17394889-1

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 C/O: EPK Tustin Date of Receipt: 02-29-2024

Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

## ASBESTOS PLM REPORT

Location: 0227-43-131, A209 Cell Window - Cell Window Caulking Black

Edeation: 0227 43 131,71207 Cen Window Cen Win	dow Cataking Black
Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity: Good	

Location: 0227-43-132, A222 Cell Window - Cell Window Caulking Black

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

Location: 0227-43-133, A23A Cell Window - Cell Window Caulking Black

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

Location: 0227-44-134, 2nd Floor N. Corridor W. End -	Red Electrical Mastic Lab ID-Version‡: 17394890-1		
Sample Layers	Asbestos Content		
Red Mastic	ND		
Composite Non-Asbestos Content: 5% Cellulose			
Sample Composite Homogeneity:	Good		

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-28-2024 C/O: EPK Tustin Date of Receipt: 02-29-2024 Re: 120316-AS, LM; 5701 8th St. Dublin CA Date of Report: 03-07-2024

#### ASBESTOS PLM REPORT

Location: 0227-44-135, 2nd Floor N. Corridor W. End - Red Electrical Mastic

Location: 0227-44-135, 2nd Floor N. Corridor W. End	• Red Electrical Mastic Lab ID-Version‡: 17394891-1	
Sample Layers	Asbestos Content	
Red Mastic	ND	
Composite Non-Asbestos Content:	5% Cellulose	
Sample Composite Homogeneity:	Good	

Location: 0227-44-136, 2nd Floor N. Corridor W. End - Red Electrical Mastic Lab ID-Version 1: 17394892-1

Sample Layers	Asbestos Content
Red Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Filed 04/05/24 Page 70 of 125 Aspestos Chain of Custody
Special Instructions: Case 4:23-cv-04155-YGR Document 246-2 Project No.: FEDERAL CODRECTIONAL INSTITUTION Project Name: DUBLIN COMP UNIT A DETENTIAN CTR 5701 8TH ST. DUPLIN CO 94568 Project Address: ☐ Analyze ALL samples. GARRIEL KLEIN Inspector:

02.28.24

RESULTS: NORCAL@ TITAN-ENVIRO.COM

Sample Date:

Send Results to:

☐ Analyze all wall system samples; Stop at first positive (>1%) for all single layer, homogenous materials (D) layer, homogenous materials (G) ☐ Other: □Unoccupied TAT: 3 hr / 6 hr / 24 hr / Other: 5 DAV

ENVIRONME ENVIRONME	HS /	Send Results to: Analysis:	PEM Bulk Asbestos An	alysis by EPA 600/R-93/116 / Other:			
Sample Nu	ımber	Sam	ple Location	Material Description	Material Locations	Quantity	
0227.23	67	UNIT & BOOF	CENTER	BLACK PENETRETTON MASTIC	UNIT A ROOF	7555	
	68	UNIT & ROCK	CENTER	Material			
	69		F CENTER	Texture/Pattern			
				Assembly/Layers			
				Friable / Non-Friable	0	003557600	
				TSI / Surf / Misc.			
				Condition: G / D / SD			
0227.24	70	UNIT & LOVE	= center	BLACK SECLANT	UNIT & RUST SKYLIGH	T SESF	
,	71	1 1	1	Material	3		
,	72	1.	1/-	Texture/Pattern			
				Assembly/Layees			
				Friable / Non-Friable			
				TSI / Surf / Misc.			
				Condition G D / SD			
0227.25	73	UNIT A ROCK	W. CENTER	HURC MASTIC GALLY	UNIT A RUST HUGE U	UTT TOSE	
our w	74	1	1 1	Material			
	75	10 6	-	Texturs/Pattern			
	10			Assembly/Laystra			
				Friable / Non-Friable			
				TSI / Surf / Misc			
				Condition: G / D / SD			

		Frial	ole / Non-Friable		
		TSI	/ Surf / Misc		
		Condit	ion: G / D / SD		
Relinquished: (sign): Received by Lab (sign):	OAKLAN	Name (print): GABRIEL K. Name (print): Sohot D ADDRESS: 1901 HARRISON STREET, S	Date/Time: 2-28  Date/Time: 7  Date/Time: 7  Date/Time: 7	-24 A Secure Dropbox □ Secure 129/24 9:50am HONE: 888-948-4826	Courier Service Page of

## Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 71 of 125 Asbestos Chain of Custody

Sample Number	r Sample Location	Material Description	Material Locations	Quantity	
	UNIT A ROUT E CENTER	BLACK ROOFSHOMASTIC	UNIT SPOOF	120SF	
0227.26 76	UNIT & ROOF CENTER	Material			
100.00		Texture/Pattern			
78	b 6 F	Assembly/Layers		MODNICAL	
		Friable / (Non-Friable)	003	557600	
		TSI / Surf / Misc	003,		
		Condition G   D / SD			
0127.27 79	LIVIT & DOCK S. WALL CENTER	LWALL TEXTURE BUFF-WHITE	UNH & REST PARAPET	780SF	
80		Material	usu		
81		T- 4 (6-44			
6/	DATE OF THE PROPERTY OF THE PR	Assembly/Layers			
		Friable / Non-Friable			
		TSI / Surf / Misc.)			
		Condition: G / D / SD			
0227-28 82	UPIT A ROOF E. WALLS. END	TON FLASHING BAULKING	UNIT & ROUT	260 SF	
82		Material			
86		Texture/Pattern			
0.		Assembly/Layers			
		Friable / Non-Friable			
		TSI / Surf / Miso			
		Condition. G / D / SD			

Sample N	umber	Sample Location	Material Description	Material Locations	Quantity
		UNIT & PLOF CENTER	ROLLED ROOF SYSTEM	UPIT & ROUT	12,000SF
	86	1 1	BUNCK		
	87	1 b b	Texture/Pattern	THOUSAND THE PROPERTY OF THE P	SHORT THE COLUMN
	01	> /	Assembly/Läyers		
			Friable / (Non-Friable	003	557600
			TSI / Surf / Misc		
			Condition: G / D / SD		
0227.30	38	SHOWER 1 S. WALL CENTER	WHITE DIM NOW THOMAS COMPUND	UPIT & INTEDIUR	1,300SF
D. C. J.	89	1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1	Material		
	90	SHOUTE 1 N. WALL CENTE	Texture/Pattern		
	91	1 1	Assembly/Layers		
	92	SHOWER 2 N. WALL CENTER	Friable / (Non-Friable		
	-		TSI / Surf / Misc.		
	Con	Condition: G / D / SD			
0227.31	93	2NO FLOWE S. CORPIDER	WHITE CEINLESTIFF 2×2	UNIT & INTERIOR	12.00 SF
022117	94	No 12 H	[Material]		
	95	2ND N. CORDIDINE	Texture/Pattern		
		F. 020	Assembly/Layers		
			Friable / Non-Friable		
	_		TSI / Surf / Misc		
			Condition: G / D / SD		

Sample Nu	mbor	Sample Location	Material Description	Material Locations	Quantity
		19T FLUX DAGROOM SE	TAN BASECAC MASTIC	UNIT & INTOLIUR	1,10035
	70	1ST FLOOR DAY ROUM SE	Material		
	97	1 ST FLOOR DAY ROOM NW	Texture/Pattern		
	98	231 12012 1744	Assembly/Layers		
			Friable / (Non-Friable	0035	57600
			TSI / Surf / Misc		2,000
			Condition: G V D / SD		
0227.33	99	A140 FLOOR CENTER	GREY VINYL FLOOR FILE	UNIT A INTERIOR	5,790
	100	N. CORKIDOR FLORR W. END	dex dies		
	101	S. CORRIDOR FLOOR WIEND	Texture/Pattern		
	101		Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misco		
			Condition G D / SD		
0227-34	107	5. CORPIDER PLOR ENTER	WHITE VILL FOR BOOTTILE	UNIT & INTERIOR	6005+
Dec 1	103	W. CORRIDOR FUDOR SIEND	9×19 months		
	INI	DAY RUOM FLOODE CENTER	Texture/Pattern		
			Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misco		
			Condition: G V D / SD		_

Sample No	ımber	Tens by	Sample I	Location	Material Description	Material Loca	tions	Quantity
0227.35		A138		CENTER	BLUE VINYLSTOPEOOR THE	UNIT & INTERIOR	- A138	1005F
077 (130)	106	1	1	1	9 "2" 4"		=32	1
	107	1		A	Texture/Pattern		70000	MONTH MANAGEMENT
	1.1	V	7	V	Assembly/Layers			
					Friable / Non-Friable		- 0035	57600
					TSI / Surf / Misc.		_	1
					Condition G / D / SD			
0227.36	108	AIIT	FLOOR	CENTER	BLACK FLOOR MASTIC	UNIT A INTERIO	R	6,370
	109	£120	FLOOR	LENTER	Material			
	110		FLOOR-		Texture/Pattern			
					Assembly/Layers			
					Friable / Non-Friable			
					TSI / Surf / Miscs			
					Condition: G D / SD			
022737	111	LAUND	M E. WAL	LCENTER	GREY CONCRETE	UNIT & lateria	re	12,000
	112	1			Material			
E	113		1.	¥	Texture/Pattern			
		-		V	Assembly/Layers			
	1				Friable / Non-Friable			
					TSI / Surf / Misc			
		1.			Condition: G / D / SD			

Sample Nu	mher		Sample Loca	ition	Material Description	Material Locations	110000	antity
	114			na centen		UNIT A INTENIOR	220	2 SF
0421.20	115	-		\	Material			
	116.	+	b	P	Texture/Pattern		MARKATAN PARKE	NEW ARLOS
	-	- V			Assembly/Layers			
					Friable / Non-Friable		0035576	500
					TSI / Surf / Misc.			
					Condition: G / D / SD			
027.39	117	W. CORPLIDE	OR CEILINI	center.	BROWN PURCE MASTIC	UNIT & INTERIOR	220	oSF.
J-6713 1	118	1	1	1	Material			
	(19	b	Þ	b	Texture/Pattern			
					Assembly/Layers			
					Friable / Mon-Friable			
					TSI / Surf / Misc.			
					Condition: G D / SD			
1227.40	120	SHOWER-Z	N. WALL	CENTER	GNEY PLOSTER	UNIT & INTERIOR	2,6	OOSF
VEZ / I	121	L		LEWER	Material			
	122	SHOWER	L N. WALL		Texture/Pattern		-	
	123			CENTER	Assembly/Layers			
	124		. WALL S		Friable / Non-Friable			
					TSI / Surf / Misc			
					Condition: G / D / SD			

Sample Nu	ımber	Sample Location	Material Description	Material Locations	Quantity
0227.41	125	LAUNDRY NE. CORPER	WHITE PIPE INSULATION	UNIT & INTERIOR LAUNDRY	130 5#
0121.41	126	1 1	Material	/	
	127	to by	Texture/Pattern		
	1.5	D D 7	Assembly/Layers		
			Friable / Non-Friable	00355	7400
			TSI / Surf / Misc.	00333	7000
			Condition G / D / SD		
0227.42	128	LAURDHY SE CORNED	TAN HUAC MOSTIC	UNIT & INTERIOR LAUNDED	465F
	129		Material		
	130	+ + +	Texture/Pattern		
	.,,,	4	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc		
			Condition: G // D / SD		
0227.43	131	209 CELL WINDOW	CELLEIND ON CAUKING	UNIT A INTERIOR	MOSF
	-	1277 LELL WINDOW	BLN 25 1/21		<u></u>
		1234 CELL WINDOW	Texture/Pattern		
	-3.5		Assembly/Layers		
	1		Friable / Non-Friable		
			TSI / Surf / Miss		
			Condition; G / D / SD		

Sample Number		- Sample Location		cation	Material Description	Material Locat	ions	Quantity
0227.44		2ND F	LOPELCOPP	IDOR WEND	RED FLECTIFICATUR/ColomASTIC	UNIT A INTERIOR	e	20SF
000199	135		-		Material			
	136		1	7	Texture/Pattern		1000 to the	UR NOT THE OWNER.
	, , ,	V	7		Assembly/Layers			
					Friable / Non-Friable		00355	7600
					TSI / Surf / Misc			1
					Condition G D / SD			
					Size/Color			
					Material			
					Texture/Pattern			
					Assembly/Layers			
					Friable / Non-Friable			
					TSI / Surf / Misc.			
					Condition: G / D / SD			
	-				Size/Color			
	$\vdash$				Material			
					Texture/Pattern			
					Assembly/Layers			
					Friable / Non-Friable			
	-				TSI / Surf / Misc.			
					Condition: G / D / SD			



Report for:

**EPK Tustin Titan Environmental Solutions, Inc.**1521 East Orangethorpe Ave, Ste B
Fullerton, CA 92831

Regarding:

Eurofins EPK Built Environment Testing, LLC Project: 120316-AS, LM; 5701 8th St, Dublin, CA

EML ID: 3558770

Approved by:

Dates of Analysis:

Asbestos PLM: 03-07-2024 and 03-08-2024

EMLab ID: 3558770, Page 1 of 24

Approved Signatory Danny Li

Service SOPs: Asbestos PLM (EPA 40CFR App E to Sub E of Part 763 & EPA METHOD 600/R-93-116, SOP EM-AS-S-1267) NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. The results relate only to the samples as received and tested. The results include an inherent uncertainty of measurement associated with estimating percentages by polarized light microscopy. Measurement uncertainty data for sample results with >1% asbestos concentration can be provided when requested.

Eurofins EPK Built Environment Testing, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024 Date of Receipt: 03-04-2024 Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

**Total Samples Submitted:** 

**Total Samples Analyzed:** 91

Total Samples with Layer Asbestos Content > 1%: 4

## Location: 0227-45 137, Roof C W. Wall S. End, Grey Wall Texture, Unit C Roof

Lab ID-Version : 17402311-1

99

Sample Layers	Asbestos Content
Gray Texture	ND
Blue Tape (Mesh)	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Good

## Location: 0227-45 138, Roof C W. Wall N. End, Grey Wall Texture, Unit C Roof

Lab ID-Version : 17402312-1

Sample Layers	Asbestos Content
Gray Texture	ND
Blue Tape (Mesh)	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Good

## Location: 0227-45 139, Roof C N. Wall Center, Grey Wall Texture, Unit C Roof

Lab ID-Version‡: 17402313-1

Sample Layers	Asbestos Content
Gray Texture	ND
Blue Tape (Mesh)	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-46 140, Roof C West Center, Black Rolled Roof System, Unit C Roof

Lab ID-Version‡: 17402314-1

EMLab ID: 3558770, Page 2 of 24

Sample Layers	Asbestos Content				
Black Roofing Shingle with Pebbles	ND				
Black Roofing Material	ND				
Black Roofing Material 2	ND				
Black Roofing Material 3	ND				
White Compound	ND				
Composite Non-Asbestos Content: 15% Glass Fibers					
Sample Composite Homogeneity: Poor					

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $<sup>\</sup>ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

EMLab ID: 3558770, Page 3 of 24

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-46 141, Roof C Center, Black Rolled Roof System, Unit C Roof

Lab ID-Version:: 17402315-1

Sample Layers	Asbestos Content
Black Roofing Shingle with Pebbles	ND
Black Roofing Material	ND
Black Roofing Material 2	ND
Black Non-Fibrous Material	ND
White Compound	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Poor

Location: 0227-46 142, Roof C North Center, Black Rolled Roof System, Unit C Roof

Lab ID-Version:: 17402316-1

Sample Layers	Asbestos Content
Black Roofing Shingle with Pebbles	ND
Black Roofing Material	ND
Black Non-Fibrous Material	ND
White Compound	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Poor

Location: 0227-47 143, Roof C W. Wall Center, Black Seam Mastic, Unit C Roof

Lab ID-Version:: 17402317-1

Sample Layers	Asbestos Content
Gray Mastic	ND
Black Mastic	7% Chrysotile
Composite Non-Asbestos Content:	2% Cellulose
Sample Composite Homogeneity:	Moderate

Comments: Samples 0227-47-144 & 0227-47-145 were not analyzed due to prior positive series.

Location: 0227-48 146, Roof C W. Wall Center, Tan Flashing Caulking, Unit C Roof

Lab ID-Version‡: 17402320-1

Sample Layers	Asbestos Content
Tan Caulk	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

EMLab ID: 3558770, Page 4 of 24

Client: Titan Environmental Solutions, Inc. C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024 Date of Receipt: 03-04-2024 Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-48 147, Roof C N. Wall Center, Tan Flashing Caulking, Unit C Roof

Lab ID-Version;: 17402321-1

Sample Layers	Asbestos Content
Tan Caulk	ND
Sample Composite Homogeneity:	Moderate

Location: 0227-48 148, Roof C S. Wall Center, Tan Flashing Caulking, Unit C Roof

Lab ID-Version‡: 17402322-1

Sample Layers	Asbestos Content
Tan Caulk	ND
Sample Composite Homogeneity:	Moderate

Location: 0227-49 149, Roof C Center, Black Penetration Mastic, Unit C Roof

Lab ID-Version:: 17402323-1

Sample Layers	Asbestos Content
Black Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-49 150, Roof C West Center, Black Penetration Mastic, Unit C Roof

Lab ID-Version:: 17402324-1

Sample Layers	Asbestos Content
Black Mastic	ND
<b>Composite Non-Asbestos Content:</b>	10% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

EMLab ID: 3558770, Page 5 of 24

Client: Titan Environmental Solutions, Inc.
C/O: EPK Tustin
Date of Sampling: 02-29-2024
Date of Receipt: 03-04-2024
Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-49 151, Roof C North Center, Black Penetration Mastic, Unit C Roof

Lab ID-Version:: 17402325-1

Sample Layers	Asbestos Content
Black Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-50 152, Roof C W. Wall Center, Tan Penetration Mastic, Unit C Roof

Lab ID-Version‡: 17402326-1

Sample Layers	Asbestos Content
Tan Mastic	ND
Black Mastic (Trace)	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-50 153, Roof C W. Wall Center, Tan Penetration Mastic, Unit C Roof

Lab ID-Version:: 17402327-1

Sample Layers	Asbestos Content
Tan Mastic	ND
Black Mastic (Trace)	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

## Location: 0227-50 154, Roof C N. Wall Center, Tan Penetration Mastic, Unit C Roof Lab ID-Version‡: 17402328-1

Sample Layers	Asbestos Content
Tan Mastic	ND
Black Mastic (Trace)	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version‡: 17402329-1

Lab ID-Version 17402330-1

Lab ID-Version 17402331-1

EMLab ID: 3558770, Page 6 of 24

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-51 155, Roof C Center, Black Roof Mastic, Unit C Roof

Sample Layers	Asbestos Content
White Non-Fibrous Material	ND
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-51 156, Roof C West Center, Black Roof Mastic, Unit C Roof

Sample Layers	Asbestos Content
White Non-Fibrous Material	ND
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-51 157, Roof C North Center, Black Roof Mastic, Unit C Roof

Sample Layers	Asbestos Content
White Non-Fibrous Material	ND
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-52 158, Roof C W. Wall S. End, Off-white Seam Mastic, Unit C Roof

Lab ID-Version‡: 17402332-1

Sample Layers	Asbestos Content
Off-White Mastic	2% Chrysotile
Composite Non-Asbestos Content: 5% Cellulose	
Sample Composite Homogeneity:	Moderate

**Comments:** Samples 0227-52-159 & 0227-52-160 were not analyzed due to prior positive series.

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-53 161, Roof C Tower NE, Black Window Sealant, Unit C Roof Tower

Lab ID-Version 17402335-1

Sample Layers	Asbestos Content
Black Sealant	ND
Sample Composite Homogeneity: Good	

Location: 0227-53 162, Roof C Tower NE, Black Window Sealant, Unit C Roof Tower

Lab ID-Version‡: 17402336-1

Sample Layers	Asbestos Content
Black Sealant	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity:	Good

Location: 0227-53 163, Roof C Tower NE, Black Window Sealant, Unit C Roof Tower

Lab ID-Version:: 17402337-1

Sample Layers	Asbestos Content
Black Sealant	ND
Sample Composite Homogeneity:	Good

# Location: 0227-54 164, Roof C Tower NW, White Window Caulking, Unit C Roof Tower

Lab ID-Version : 17426529-1

EMLab ID: 3558770, Page 7 of 24

Sample Layers	Asbestos Content
White Caulk	ND
Sample Composite Homogeneity: Good	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc. C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024 Date of Receipt: 03-04-2024 Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-54 165, Roof C Tower NW, White Window Caulking, Unit C Roof Tower

Lab ID-Version‡: 17426530-1

Sample Layers	Asbestos Content
White Caulk	ND
Sample Composite Homogeneity: Good	

#### Location: 0227-54 166, Roof C Tower NW, White Window Caulking, Unit C Roof Tower

Lab ID-Version : 17426531-1

Sample Layers	Asbestos Content
White Caulk	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-55 167, Roof C N. Wall Center, Grev Mortar, Unit C Roof

Lab ID-Version‡: 17426532-1

Sample Layers	Asbestos Content
Gray Mortar	ND
Composite Non-Asbestos Content:	< 1% Cellulose
Sample Composite Homogeneity:	Moderate

### Location: 0227-55 168, Roof C N. Wall Center, Grey Mortar, Unit C Roof

Lab ID-Version‡: 17426533-1

EMLab ID: 3558770, Page 8 of 24

Sample Layers	Asbestos Content
Gray Mortar	ND
Composite Non-Asbestos Content:	< 1% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

EMLab ID: 3558770, Page 9 of 24

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-29-2024 C/O: EPK Tustin

> Sample Layers Gray Mortar

Date of Receipt: 03-04-2024

Re: 120316-AS, LM; 5701 8th St, Dublin, CA Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-55 169, Roof C N. Wall Cen

Roof C N. Wall Center, Grey Mor	tar, Unit C Roof	Lab ID-Version‡: 17426534-1
ample Layers	Asbestos Conte	nt
Gray Mortar	ND	
<b>Composite Non-Asbestos Content:</b> <	1% Cellulose	

Location: 0227-56 170, Roof C Tower S. Wall, Grey Flashing Caulking, Unit C Roof

Sample Composite Homogeneity: | Moderate

**Tower** Lab ID-Version :: 17426535-1

Sample Layers	Asbestos Content
Gray Caulk	ND
Sample Composite Homogeneity:	Moderate

# Location: 0227-56 171, Roof C Tower S. Wall, Grey Flashing Caulking, Unit C Roof

**Tower** Lab ID-Version 17426536-1

Sample Layers	Asbestos Content
Gray Caulk	ND
Sample Composite Homogeneity:	Moderate

# Location: 0227-56 172, Roof C Tower W. Wall, Grey Flashing Caulking, Unit C Roof

**Tower** Lab ID-Version 1: 17426537-1

Sample Layers	Asbestos Content
Gray Caulk	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

# Location: 0227-57 173, Receiving/Discharge S. Wall Center, White Dry Wall/Joint

Compound, Unit C Interior

Lab ID-Version:: 17426538-1

Sample Layers	Asbestos Content
Cream Joint Compound	ND
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose
Sample Composite Homogeneity:	Moderate

# Location: 0227-57 174, Processing Bathroom N. Wall W. End, White Dry Wall/Joint

Compound, Unit C Interior

Lab ID-Version‡: 17426539-1

Sample Layers	Asbestos Content
Cream Joint Compound	ND
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content: 3% Cellulose	
Sample Composite Homogeneity:	Moderate

# Location: 0227-57 175, Library E. Wall N. End, White Dry Wall/Joint Compound, Unit

C Interior

Lab ID-Version‡: 17426540-1

Sample Layers	Asbestos Content
Cream Joint Compound	ND
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose
Sample Composite Homogeneity:	Moderate

## Location: 0227-57 176, H.R. Manager E. Wall N. End, White Dry Wall/Joint Compound,

Unit C Interior

Lab ID-Version:: 17426541-1

Sample Layers	Asbestos Content
Cream Joint Compound	ND
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

## Location: 0227-57 177, H.R. Assistant E. Wall Center, White Dry Wall/Joint Compound,

Unit C Interior

Lab ID-Version‡: 17426542-1

Sample Layers	Asbestos Content
Cream Joint Compound	ND
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose
Sample Composite Homogeneity:	Moderate

# Location: 0227-57 178, Waiting E. Wall Center, White Dry Wall/Joint Compound, Unit

C Interior

Lab ID-Version‡: 17426543-1

Sample Layers	Asbestos Content
Cream Joint Compound	ND
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose
Sample Composite Homogeneity:	Moderate

# Location: 0227-57 179, H.R. Manager W. Wall Center, White Dry Wall/Joint Compound,

Unit C Interior

Lab ID-Version‡: 17426544-1

Sample Layers	Asbestos Content
Cream Joint Compound	ND
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose
Sample Composite Homogeneity:	Moderate

### Location: 0227-58 180, Receiving/Discharge Ceiling N., White Ceiling Tile 9" x 9", Unit

C Interior Lab ID-Version‡: 17426545-1

Sample Layers	Asbestos Content
Gray Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	
	40% Glass Fibers
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-29-2024 C/O: EPK Tustin Date of Receipt: 03-04-2024

Re: 120316-AS, LM; 5701 8th St, Dublin, CA Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-58 181, Receiving/Discharge Ceiling N., White Ceiling Tile 9" x 9", Unit

**C** Interior Lab ID-Version 1: 17426546-1

Sample Layers	Asbestos Content
Gray Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	
	40% Glass Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-58 182, Receiving/Discharge Ceiling N., White Ceiling Tile 9" x 9", Unit

**C** Interior Lab ID-Version : 17426547-1

Sample Layers	Asbestos Content
Gray Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	
	40% Glass Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-59 183, Receiving/Discharge Ceiling N., Brown Puck Mastic, Unit C

Interior Lab ID-Version 1: 17426548-1

Sample Layers	Asbestos Content
Brown Mastic	ND
Sample Composite Homogeneity:	Moderate

## Location: 0227-59 184, Receiving/Discharge Ceiling N., Brown Puck Mastic, Unit C

**Interior** Lab ID-Version 1: 17426549-1

	End 15 (15:501, 17:200.)
Sample Layers	Asbestos Content
Brown Mastic	ND
Sample Composite Homogeneity	: Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc. C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024 Date of Receipt: 03-04-2024 Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-59 185, Receiving/Discharge Ceiling N., Brown Puck Mastic, Unit C

Interior

Lab ID-Version‡: 17426550-1

Sample Layers	Asbestos Content
Brown Mastic	ND
Sample Composite Homogeneity:	Moderate

#### Location: 0227-60 186, Counter E. Wall Center, Black Window Caulking, Unit C Interior

Lab ID-Version : 17426551-1

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

#### Location: 0227-60 187, Counter E. Wall Center, Black Window Caulking, Unit C Interior

Lab ID-Version : 17426552-1

EMLab ID: 3558770, Page 13 of 24

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

# Location: 0227-60 188, Sally Port S. Wall Center, Black Window Caulking, Unit C

Interior Lab ID-Version‡: 17426553-1

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-61 189, W. Corridor S. Wall Center, Cove Base Tan Mastic, Unit C

Interior Lab ID-Version‡: 17426554-1

Sample Layers	Asbestos Content
Yellow Mastic	ND
Composite Non-Asbestos Content:	< 1% Cellulose
	< 1% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-61 190, W. Corridor S. Wall Center, Cove Base Tan Mastic, Unit C

Interior Lab ID-Version:: 17426555-1

Sample Layers	Asbestos Content
Yellow Mastic	ND
Composite Non-Asbestos Content:	
	< 1% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-61 191, Witness/Attoney Room N. Wall W. End, Cove Base Tan Mastic,

Unit C Interior

Lab ID-Version‡: 17426556-1

Sample Layers	Asbestos Content
Yellow Mastic	ND
Composite Non-Asbestos Content:	
	< 1% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

## Location: 0227-62 192, Tower E. Center, Red Vinvl Floor Tile 9" x 9", Unit C Interior Lab ID-Version: 17426557-1

200mion 022: 02 123, 10 Hot 24 00mion, 1100 High 11001 1100 High 11001 Hot 11001 High 11001 Hot 11001 High 110		
Sample Layers	Asbestos Content	
Red Floor Tile	ND	
Black Mastic	ND	
Composite Non-Asbestos Content: < 1% Cellulose		
Sample Composite Homogeneity:	Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-62 193, Witness/Attoney Room Center, Red Vinyl Floor Tile 9" x 9", Unit

C Interior

Lab ID-Version‡: 17426558-1

Sample Layers	Asbestos Content	
Red Floor Tile	ND	
Black Mastic	ND	
Composite Non-Asbestos Content: < 1% Cellulose		
Sample Composite Homogeneity:	Moderate	

## Location: 0227-62 194, Waiting S. Center, Red Vinyl Floor Tile 9" x 9", Unit C Interior

Lab ID-Version : 17426559-1

Sample Layers	Asbestos Content	
Red Floor Tile	ND	
Black Mastic	ND	
Composite Non-Asbestos Content: < 1% Cellulose		
Sample Composite Homogeneity:	Moderate	

# Location: 0227-63 195, Witness/Attoney Room Center, White Vinyl Floor Tile, Unit C

Interior Lab ID-Version‡: 17426560-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic	ND
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Poor

# Location: 0227-63 196, Witness/Attoney Room Center, White Vinyl Floor Tile, Unit C Interior

Lab ID-Version‡: 17426561-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic	ND
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-63 197, Witness/Attoney Room Center, White Vinyl Floor Tile, Unit C

Interior Lab ID-Version‡: 17426562-1

Sample Layers	Asbestos Content
White Floor Tile	ND
Yellow Mastic	ND
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Poor

Location: 0227-64 198, H.R. Manager Center, Black Floor Mastic, Unit C Interior Lab ID-Version‡: 17426563-1

Sample Layers	Asbestos Content
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-64 199, H.R. Assistant Center, Black Floor Mastic, Unit C Interior Lab ID-Version:: 17426564-1

Sample Layers	Asbestos Content
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-64 200, Tower Center E., Black Floor Mastic, Unit C Interior

Lab ID-Version‡: 17426565-1

Sample Layers	Asbestos Content
Black Mastic	ND
Composite Non-Asbestos Content:	5% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-65 201, Kitchen Center N., White Ceiling Tile 2 x 4 Smooth, Unit C

Interior Lab ID-Version‡: 17426566-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	
	3% Vermiculite < 1% Glass Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-65 202, Kitchen Center N., White Ceiling Tile 2 x 4 Smooth, Unit C

Interior Lab ID-Version‡: 17426567-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose 3% Vermiculite < 1% Glass Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-65 203, Kitchen Center N., White Ceiling Tile 2 x 4 Smooth, Unit C

Interior Lab ID-Version‡: 17426568-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Composite Non-Asbestos Content:	3% Cellulose 3% Vermiculite < 1% Glass Fibers
Sample Composite Homogeneity:	Moderate

#### Location: 0227-66 204, Kitchen W. Wall S. End, Red Electrical Mastic, Unit C Interior Lab ID-Version‡: 17426569-1

Sample Layers	Asbestos Content
Red Mastic	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-66 205, Tower S. Wall E. End, Red Electrical Mastic, Unit C Interior Lab ID-Version‡: 17426570-1

Sample Layers	Asbestos Content
Red Mastic	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity:	Moderate

## Location: 0227-66 206, Waiting N. Wall W. End, Red Electrical Mastic, Unit C Interior

Lab ID-Version 1: 17426571-1

Sample Layers	Asbestos Content
Red Mastic	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity:	Moderate

Location: 0227-67 207, Maintenance N. Wall Center, Grey Flaster, Unit C Interior Lab ID-Version‡: 17426572-1

Sample Layers	Asbestos Content	
White Plaster	ND	
Gray Plaster	ND	
Composite Non-Asbestos Content: < 1% Cellulose		
Sample Composite Homogeneity:	Moderate	

#### Location: 0227-67 208, Daily Stores N. Wall Center, Grey Flaster, Unit C Interior Lab ID-Version:: 17426573-1

Sample Layers	Asbestos Content
White Plaster	ND
Gray Plaster	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Lab ID-Version †: 17426574-1

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

### ASBESTOS PLM REPORT

Location: 0227-67 209, Kitchen E. Wall Center, Grey Flaster, Unit C Interior

Education: 0227 07 209, Interior E. Wan Center, Grey Flagter, Omt C Interior	
Sample Layers	Asbestos Content
White Plaster	ND
Gray Plaster	ND
Composite Non-Asbestos Content:	< 1% Cellulose
Sample Composite Homogeneity	Moderate

Location: 0227-67 210, Staff Restroom, E. Wall Center, Grey Flaster, Unit C Interior Lab ID-Version 17426575-1

Sample Layers	Asbestos Content	
White Plaster	ND	
Gray Plaster	ND	
Composite Non-Asbestos Content: < 1% Cellulose		
Sample Composite Homogeneity: Moderate		

Location: 0227-67 211, Daily Stores S. Wall W. End, Grey Flaster, Unit C Interior Lab ID-Version:: 17426576-1

Sample Layers	Asbestos Content
White Plaster	ND
Gray Plaster	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity:	Moderate

Location: 0227-68 212, Daily Stores Center, Tan Fire Proofing, Unit C Interior

Lab ID-Version‡: 17426577-1

Sample Layers	Asbestos Content
Tan Fireproofing	ND
<b>Composite Non-Asbestos Content:</b>	50% Glass Fibers
	< 1% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-68 213, Laundry Office Center, Tan Fire Proofing, Unit C Interior Lab ID-Version:: 17426578-1

Sample Layers	Asbestos Content
Tan Fireproofing	ND
Composite Non-Asbestos Content:	50% Glass Fibers
_	< 1% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-68 214, Maintenance Center, Tan Fire Proofing, Unit C Interior

Sample Layers	Asbestos Content
Tan Fireproofing	ND
Composite Non-Asbestos Content:	50% Glass Fibers < 1% Cellulose
Sample Composite Homogeneity:	

## Location: 0227-69 215, Daily Stores Center N., Off-white Pipe Insulation, Unit C Interior

Lab ID-Version 1: 17426580-1

Lab ID-Version‡: 17426579-1

Sample Layers	Asbestos Content
Off-White Texture	ND
Yellow Insulation	ND
Composite Non-Asbestos Content:	90% Glass Fibers
Sample Composite Homogeneity:	Moderate

### Location: 0227-69 216, Daily Stores Center N., Off-white Pipe Insulation, Unit C Interior

Lab ID-Version : 17426581-1

Sample Layers	Asbestos Content
Off-White Texture	ND
Yellow Insulation	ND
Composite Non-Asbestos Content: 90% Glass Fibers	
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-69 217, Daily Stores Center N., Off-white Pipe Insulation, Unit C Interior

Lab ID-Version‡: 17426582-1

Lab ID-Version : 17426586-1

Sample Layers	Asbestos Content
Off-White Texture	ND
Yellow Insulation	ND
Composite Non-Asbestos Content: 90% Glass Fibers	
Sample Composite Homogeneity:	Moderate

# Location: 0227-70 218, Daily Stores E. Wall N. End, Off-white Door Seam Mastic, Unit C

Interior Lab ID-Version‡: 17426583-1

Sample Layers	Asbestos Content
Off-White Mastic	2% Chrysotile
Sample Composite Homogeneity: Moderate	

Comments: Sample 0227-70 219 & 0227-70 220 were not analyzed due to prior positive series.

#### Location: 0227-71 221, Loading Area Center, Grev Concrete, Unit C Interior

, 8 / <b>i</b>	,
Sample Layers	Asbestos Content
Gray Concrete	ND
Composite Non-Asbestos Content:	< 1% Cellulose
Sample Composite Homogeneity:	Moderate

#### Location: 0227-71 222, Loading Area Center, Grey Concrete, Unit C Interior Lab ID-Version‡: 17426587-1

Sample Layers	Asbestos Content
Gray Concrete	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc. Date of Sampling: 02-29-2024 C/O: EPK Tustin Date of Receipt: 03-04-2024 Re: 120316-AS, LM; 5701 8th St, Dublin, CA Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

Location: 0227-71 223, Loading Area Center, Grev Concrete, Unit C Interior

Location: 0227-71 223, Loading Area Center, Grey Con	acrete, Unit C Interior Lab ID-Version‡: 17426588-1
Sample Layers	Asbestos Content
Gray Concrete	ND
Composite Non-Asbestos Content:	< 1% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 0227-72 224, Secretary SE, Yellow Carpet Glue, Unit C Interior, Office Lab ID-Version 1: 17426589-1

, , , , ,		
Sample Layers	Asbestos Content	
Yellow Mastic	ND	
Composite Non-Asbestos Content:	< 1% Cellulose	
	< 1% Synthetic Fibers	
Sample Composite Homogeneity:	Good	

#### Location: 0227-72 225, Superindependant SE, Yellow Carpet Glue, Unit C Interior, Office

	•
Sample Layers	Asbestos Content
Yellow Mastic	ND
Composite Non-Asbestos Content:	< 1% Cellulose
<u>-</u>	< 1% Synthetic Fibers
Sample Composite Homogeneity:	Good

#### Location: 0227-72 226, Case Worker NW, Yellow Carpet Glue, Unit C Interior, Office Lab ID-Version 1: 17426591-1

Sample Layers	Asbestos Content
Yellow Mastic	ND
Composite Non-Asbestos Content:	< 1% Cellulose
	< 1% Synthetic Fibers
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $\ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Lab ID-Version : 17426590-1

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc.

C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024

Date of Receipt: 03-04-2024

Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

# Location: 0227-73 227, Kitchen Center N, White Ceiling TIle 2 x 4 Textured, Unit C

Interior Lab ID-Version‡: 17426592-1

Sample Layers	Asbestos Content
Gray Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose
_	40% Glass Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-73 228, Kitchen Center N, White Ceiling TIle 2 x 4 Textured, Unit C

Interior Lab ID-Version‡: 17426593-1

Sample Layers	Asbestos Content
Gray Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose
	40% Glass Fibers
Sample Composite Homogeneity:	Moderate

# Location: 0227-73 229, Kitchen Center N, White Ceiling TIle 2 x 4 Textured, Unit C

Interior Lab ID-Version‡: 17426594-1

Sample Layers	Asbestos Content
Gray Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose 40% Glass Fibers
Sample Composite Homogeneity:	

# Location: 0227-74 230, Boiler Room S. Center, Black Duct Seam Mastic, Unit C Interior

Lab ID-Version : 17426595-1

Sample Layers	Asbestos Content
Black/White Mastic	5% Chrysotile
Sample Composite Homogeneity: Moderate	

Comments: Sample 0227-74 231 & 0227-74-232 were not analyzed due to prior positive series.

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (800) 651-4802 www.eurofinsus.com/Built

Client: Titan Environmental Solutions, Inc. C/O: EPK Tustin

Re: 120316-AS, LM; 5701 8th St, Dublin, CA

Date of Sampling: 02-29-2024 Date of Receipt: 03-04-2024 Date of Report: 03-08-2024

#### ASBESTOS PLM REPORT

#### Location: 0227-75 233, Boiler Room E. Wall Center, Tan Base Cove Mastic, Boiler Room

Unit C

Sample Layers	Asbestos Content
Tan Mastic	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity: Moderate	

# Location: 0227-75 234, Boiler Room E. Wall Center, Tan Base Cove Mastic, Boiler Room

J**nit C** Lab ID-Version‡: 17426599-1

Sample Layers	Asbestos Content
Tan Mastic	ND
Composite Non-Asbestos Content:	< 1% Cellulose
Sample Composite Homogeneity:	Moderate

# Location: 0227-75 235, Boiler Room E. Wall Center, Tan Base Cove Mastic, Boiler Room

Unit C

Sample Layers	Asbestos Content
Tan Mastic	ND
Composite Non-Asbestos Content: < 1% Cellulose	
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Sample Numbe	r Sam	ple Location	Material Des	cription	Material Lo	ocations Quantity
101011041	Analysis:	PLM Bulk Asbestos /	Analysis by EPA 600/R-93/116 / Other:			
ENVIRONMENTAL	Send Results to:		@TITAN-ENVIRO.COM	TAT: 3 hr / 6	hr / 24 hr / Other: 5 DAY	Occupied Unoccupied
FITAI	Sample Date:	02.29.24		☐ Other:		
/	Inspector:	GABRIEC 16		☐ Analyze A	LL samples.	
	Project Address:		ST DUBLIN, CA 9456	▼ Stop at firs		l system samples and/or single
	Project Name:	PEDERAL C	orrectionse exstitution	Analyze al	I wall system samples; Stop a nomogenous materials (D)	t first positive (>1%) for all
	Project No.:			Copecial Align	uctions:	
	Cas	se 4:23-cv-0415	5-YGR <sub>M</sub> Document 246-2	Filed 04/05/24	4 Page 102 of 125	Asbestos Chain of Custody

Sample Number		r Sample Location		Material Description	Material Locat	tions Quant
0227:45	137	RUF C W. W	IFLL S.END	GREY WALL TEXTURE	LAIT C ROOF	900
	138	ROUT C W.W	ble N. END	Material		
	137	ROUTE N. W	ALL CENTER	Testare/Patters		
				Assembly/Layers		
				Friable / Non-Friable		003558770
				TSI / Surf / Misc		1
				Condition G D / SD		
0227.46	140	ROOF C WES	T CENTER	BLACK ROLLED RECT SYSTEM	UNITE ROOF	9,0008
	141	i c	ENTER	Material		
	142		RIH CENTER	Texture/Pattern		
		,		Assembly/Luyers		
				Friable / Non-Friable		
				TSI / Surf / Misc		
				Condition: G / D / SD		
0227.47	143	RUUT C W.	wou center	BLACK SEAM MASTIC	UNIT C ROOF	3055
	144	4 4	+	Material		
	145	DOUT C N.	WALL CENTER	Texture/Pattern		
				Assembly/Layers		
		12		Friable / Non-Eriable		
				TSI / Surf / Misc.		
				Condition G / D / SD		

		Friable / Non-Eriable	
		TSI / Surf / Misc.	
		Condition: G / D / SD	
Relinquished: (sign):  Received by Lab (sign):	Name (print):  Name (print):	Date/Time: 3/h 4	cure Dropbox 🗆 Secure Courier Service
,	OAKLAND ADDRESS: 1901 HARRIST	ON STREET, SUITE 100, OAKLAND, CA 94612 * PHONE: 888-948	-4826 Page / of //

# Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 103 of 125 sbestos Chain of Custody

Cample No	mhor	Sample Location	Material Description	Material Locations	Quantity
Sample Number		RUFC W.WALL CENTER	TAN FLASHING BERLKING	CNIT C ROOF	500 St
0227.48		N. WALL CENTER	Material		
	147		Texture/Pattern		
	148	& S. WALL CENTER	Assembly/Layers		17801
				<u></u>	
			Friable / Non-Friable		003559330
			TSI / Surf Misc.		003558770
			Condition: G / D / SD		
022749	149	ROUF C CENTER	BLACK PENETERFIED MASTIC	LAIT CROOF	855F
	150	I WEST CENTER	Material		
	151	17 NOWTH CENTER	Texture/Pattern		
	1.21		Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		
0227-50	452	RUFT C W. WOLL CENTER	TAN PENETREBATION MASTIC	init a poot	105F
0001	153	1 1 1	Material		
	154	N. WALL CENTER	Lexture/Pattern		
	1073	A WHIL CONTER	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
	-		Condition: G D / SD		

# Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 104 of 125\sbestos Chain of Custody

Sample N	umber	Sample Location	Material Description	Material Locations	Quantity
0227.51	155	ROOF C CENTR	BLACK RUFFORMASTIC	UNIT C ROOF	100SF
	15.6	WEST CENTER	Material		
	157	L NORTH CENTER	Texture/Pattern		
		V	Assembly/Layers		
			Friable / Non-Friable	003	3558770
			TSI / Surf / Misc.		
			Condition: G 1) D / SD		
027.52	168	RUOF C W. WALL S. END	OTT-WHITE SCAUNCE/WHYASTIC	UNITE BOOK	205F
	159	1 1 1	Material		
	160	H + +	Texture/Pattern		
		7	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		
0227.453	161	RUCE C TOWER NE	BLACK WINDOW SEGLANT	UNIT CROST TOWER	1205F
	162	1 1 1	Material		
,	163	6 6 6	Texture/Pattern		
	100		Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		

# Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 105 of 125\sbestos Chain of Custody

Sample Nu	mber	Sample Location	Material Description	Material Locations	Quantity	
	64	ROOF C TOWER NW	WHITE WINDSON EAULKING	LATT C ROOF TOUCK	165F	
	145		Tekture/Pattern		1	
	166	b + +	susembly/Layers		Managara	
		<u> </u>	Friable / (Non-Friable	003	558770	
			TSI / Surf / Misc.		220110	
			Condition: G D / SD			
0227.56	167	RUCK C N. WALL CENTER	GREY MEXTERIOR	Upit a ROOF	3USF	
	168	1 1	Material			
	169	Texture/Pattorn	Texture/Pattern			
			Assembly/Layers			
			Friable / Non-Friable			
			TSI / Surf / Misc.			
			Condition: G / D / SD			
0227.56	170	POUT C TOWER S. WALL	GREY FLASHINGE COMMUNING	UNITE DOOF TOUCK	40 SF	
	171	1 4 4	Material			
	172	touth windle	Texture/Pattern			
			Assembly/Layers			
			Friable / Non-Friable			
			TSI / Surf / Misc			
			Condition: G // D / SD			

Cample No	mher	Sample Location	Material Description	Material Locations	Quantity
Sample Number 6227 57 173		Sunfort wet		UNIT CINTERIOR	10,960
0221 51	174	PROCESSING N.WKL W. END	Material		I.
	175	LIBRARY E. WALL N. END	Texture/Pattern		
	17.6	H. R. MANAGER E. WALL N. TND	Assembly/Layers	00355	8770
	177	H. R. ASSISTANT E. WALL CENTER	Friable / Non-Friable		
	178	WAITING E. WELL CENTER	TSI / Surf / Misc.		
	179	H.R. MANAGER W. WALL CENTE	Condition: G / D / SD		
		RELEVINA/DISCHPRIGE CEILING N.	WHITE CELING STILL 9"X9"	ONIT C INTEXION	1,7005
	181		Material		
	182	b b b	Texture/Pattern		-
	.00		Assembly/Layers		
			Friable Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		
0227.56	183	RECEVINA/DISCHARGE	EXANN PUERO MASTIC	UNIT CINTERIOR	1,7005
	184	1 1 1	Material		
	185	12 12 12	Texture/Pattern		
		72	Assembly/Layers *		
			Friable / (Non-Friable		
			TSI / Surf / Misc.		
			Condition: G D / SD		

Sample Number		Sample Location	Material Description	Material Locations	Quantity
			BLECK WINDOWS CAUKING	UNIT C INTERIOR	1,2505#
2001-00	187	1 ,/ ,/	Material		
		SALLY POILT S. WALL CENTER	Texture/Pattern	T T T T T T T T T T T T T T T T T T T	
	120	, and the same of	Assembly/Layers		
			Friable / Non-Friable	00	3558770
			TSI / Surf / Mise.		T.
			Condition G D / SD		
	189	W. CORRIDOR S. WALL CENTER	- CONE BASE PARTY MASTIC	YNITC INTERIOR	1,9005#
	190		Material		
	191	WITTHESS /ATTORNEY AM N. NAK W. END	Texture/Pattern		
	6.4.	P. DACE W. CPU	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc		
			Condition: 6 + D / SD		
0227.62	107	TOWER E. LENTER	RED VIMILSTABOR THE	YNIT CINTERIOR	3,200SF
000100	193	WITNESS / ATTORTEY RM CENTER	d while		
	194	WHITING S. CENTER	Texture/Pattern		
	1.1.7		Assembly/Layers		
	_		Friable / Non-Friable		
			TSI / Surf / Miscs		
			Condition: G J D / SD		

# 

Sample Nu	ımber	Sample Location	Material Description	Material Locations	Quantity
0277.63		WITNERS/ATTORNEY RM CENTER	WAITE VINGE FLOOR TILE	UNIT C INTERIOR	300SF
024.65	196	CENTE	Material		
	197		Texture/Pattern		
	I=C.C	7 7	Assembly/Layers		
			Friable / Non-Friable	003	3558770
			TSI / Surf / Misc.		
			Condition: G / D / SD		
227.64	195	H.R. MANABER CENTER	BLACK FLESTIGORMASTIC	UNIT CINTERIOR	3,400°
arrived	199	H.R. ASSISTAT CENTER-	Material		
	200	TOWER CENTER E.	Texture/Pattern		
	200		Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		
U227-65	201	KITCHEN CENTER N.	WHITE CEILING THE 2x4	UNIT CINTERIOR	2,220SF
	202		SMESTH		
	203	b b b	Texture/Pattern		
		-	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Miso		
			Condition G / D / SD		

Sample Number			Material Description  RED ELECTRICAL MASSIC	Material Locations	Quantity
				UNIT CINFELLION	755F
0227,66	204	KIRHEN W. WALL S. END	RED ELECTRICAL MASSIC		
	205	TOWER S. WALL E. END	Texture/Pattern		
	206	WAITING W. NALL WIEND	TOOLS IN TOUR REC		THE RESIDENCE OF STREET
			Assembly/Layers		
			Friable / Non-Friable		003558770
			TSI / Surf / Misc,		
			Condition: G D / SD		
0227.67	207	MAINTENANCE N. WALL CENTER	GREY PLASTER Color	UNIT CINTERIOR	4,200SF
	208	PAILY STURES L. WALL CENTER	Material		
		KITCHEN E. WALL CENTER	Texture/Pattern		
	210	- F	Assembly/Layers		
	211	PAILY STORES S. WALL W. FHD	Friable / Non-Friable		
	211		TSI / Surf / Misc		- 1
	-		Condition G D / SD		
0217-68	212	PAILY STURES CENTER	TAN FIRE PRESENING	UNITC INTERIOR	200 SF
	213	LAUNDRY BENTER	Material		
	214	- 1. ディモンデリー	Texture/Pattern		
	217		Assembly/Layers		
	+		Friable Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		

		C	Material Description	Material Locations	the state of the s
Sample Number		Sample Location  DAILY STORTS CENTER N.	OFF-WHITE PIPESISPHOTELLATION	UNIT C INTERIOR	850 SF
0227.69 219	219	DAILY STORE - CENTER N.	Material		
	216	1	Texture/Pattern		
	217	b b b	Assembly/Layers		
			Friable / Non-Friable		003558770
			TSI / Surf / Misc.		
			Condition: G // D / SD		
	To the same	DAILY STORES E. WALL NEAD	OFF-WITE DOUBLE/GOSAM MOSTIC	UNIT C INTERIOR	8655F
227.70	2.0	KITCHEN E. WALL S. END	Material		
	219	KIRHEN S. WALL CENTER	Texture/Pattern		
	220	ETENER S. WALL CO.	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G D / SD		
	221	LOLDING ANES CENTER	and continue	UNITE INTERIOR	13500
027.71			Material		
	222		Texture/Pattern		
	223	6 6 7	Assembly/Layers		
			Friable / Non-Friable		
	-		TSI / Surf / Misc		
	-		Condition G / D / SD		

## Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 111 of 125 sbestos Chain of Custody

Sample Number		Sample Location	Material Description	Material Locations	Quantity
0227.72 224			TELLOW CANDET GLUE	UNIT C PATERIOR	1,200 SF
		SUPERLATENDANT SE	Material	OFFICES	
	de	CASE WORKER NW	Texture/Pattern		1
- 2	00		Assembly/Layers		
	-		Friable Non-Friable	003	558770
			TSI / Surf / Misc	003	)))))
			Condition G D / SD		
0227-73 227		KIRCHEN CENTER N	WHITE CELLIG TILE 2x4	UNIT CINTERIOR	1,700SF
	228		restricted		
	229	b b b	Texture/Pattern		
		b b b	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc.		
			Condition: G / D / SD		
200 760	12.2	BOILER ROOM S. CEATER	BLACK DICTIONS BOM MOSTIC	UNIT C INTERIOR	2505F
	231	1	Material		
	-		Texture/Pattern		
	232	7 0 1	Assembly/Layers		
			Friable / Non-Friable		
			TSI / Surf / Misc		
			Condition: G P D / SD		

## Case 4:23-cv-04155-YGR Document 246-2 Filed 04/05/24 Page 112 of 125/sbestos Chain of Custody

Sample Number	Sample Location	Material Description	Material Locations	Quantity
	FORER ROOM E. WALL CENTER	The BASE COUS OMBSTIC	BOILER ROOM UNIT C	20SF
	FORCE ROOM C. WAS CONTE	Material		
234		Texture/Pattern		
2397	b + 6	Assembly/Layers		
		Friable / Non-Friable		1
		TSI / Surf / Misc.	1810	03558770
		Condition G / D / SD	MINIM	
		Size/Calor	0035	
		Material		
		Texture/Pattern		
		Assembly/Layers		
		Friable / Non-Friable		
		TSI / Surf / Misc.		
		Condition: G / D / SD		
		Size/Color		
		Material		
		Texture/Pattern		
		Assembly/Layers		
		Friable / Non-Friable		
		TSI / Surf / Misc.		
		Condition: G / D / SD		




Asbestos-Containing Materials Survey Report Federal Correctional Institution – Dublin Camp Detention Center Units A, B, and C 5701 8<sup>th</sup> Street, Dublin, California 94568 Project No. 120316-AS March 14, 2024

## ATTACHMENT II


**CAD FLOOR PLAN DRAWINGS** 








1521 E. Orangethorpe Ave, Suite B Fullerton, California 92831 Phone: (888) 948-4826






120316 - AS LM

02/27/24


SITE PLAN


01













Asbestos-Containing Materials Survey Report Federal Correctional Institution – Dublin Camp Detention Center Units A, B, and C 5701 8<sup>th</sup> Street, Dublin, California 94568 Project No. 120316-AS March 14, 2024

## **ATTACHMENT III**

**INSPECTOR CERTIFICATION(S)** 





